

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

25-Mar-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6047 R

1 pc	Wheel cover
1 pc	Rear bumper
1 pc	Rear bumper o/s side bracket
1 pc	Rear o/s rim
1 pc	Rear o/s lower arm
1 pc	Rear o/s assist arm
1 pc	Rear o/s trailing arm
1 pc	Rear o/s shock absorber
1 pc	Rear o/s knuckle bearing
1 pc	Rear o/s knuckle arm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	346.40	cut
\$	459.40	Rp
\$	33.10	X
\$	1,091.50	X
\$	393.10	?
\$	92.80	X
\$	121.00	X
\$	230.50	X
\$	454.00	?
\$	386.90	?
\$	3,608.70	346.40
\$	721.74	277.12
\$	2,886.96	

S/NETT

1 set	Rear bumper clips	\$	48.00	X nn
1 set	o/s door stickers	\$	100.00	gone
1 pc	Rear o/s fender sticker	\$	60.00	gone
1 pc	Rear o/s tyre	\$	200.00	X
1 set	Rear o/s fender inner shield clips	\$	28.00	X
1 set	Sealant	\$	50.00	X
	To dismantle and replace the rear o/s undercarriage	\$	250.00	100? plus X nn
	To check rear o/s wheel alignment	\$	80.00	✓
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X nn,
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30.
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender etc	\$	800.00	400
	To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper	\$	800.00	600
	To apply rustproof on repaired panels	\$	150.00	X 1110.
		\$	5,752.96	

Tamph 97495749
up: 25/3/21 @ 450pm
p/p Resurvey new parts, after repair.
03 days
tamph @ lkkauto.com.

277.12
120
1110
\$1507.12
3 days #