

Not Adult
LH
29/3/21
L/S 2
4 days
Highly Htt



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Yeo Cheng Chuan

Date : 26 March 2021

Estimate To Repair FBM5087A - Yamaha SNIPER T150
Chassis No : MH3UG0740H0066661

29/03/2021 c (vow)

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 set	side mirror AB cut	\$ 90
02	1 pc	clutch lever cut	\$ 65.00
03	1 pc	handle balancer cut	\$ 35.00
04	1 pc	handle bar	\$ 130
05	1 pc	n/s front foot rest cut	\$ 48
06	1 pc	n/s front foot rest bracket cut	\$ 150.00
07	1 pc	o/s rear foot rest bracket cut	\$ 150.00
08	1 pc	luggage box cut	\$ 600.00
09	1 pc	luggage box bracket cut	\$ 120.00
10	2 ps	both rear tail side cover @ \$170.00 cut	\$ 340.00
11	1 pc	rear mudguard assy D.S	\$ 120
12	1 pc	rear numberplate lamp cut	\$ 50.00
13	1 pc	rear tail lamp cut	\$ 95.00
14	1 pc	rear number plate cut	\$ 20.00
15	1 pc	number plate bracket cut	\$ 50.00
16	1 pc	exhaust cap cut	\$ 75.00
17	1 pc	rear wheel rim cut	\$ 450.00
18	1 pc	rear disc rotor cut	\$ 75.00
19	1 set	yamaha sniper sticker cut	\$ 45.00
20	1 pc	gear lever assy cut	\$ 90
21	1 pc	n/s gear cover cut	\$ 75.00
		Less 10 %	\$ 2,970.00
			\$ 2,673.00
		<u>SPECIAL NETT ITEMS</u>	
22	1 pc	rear tyre cut	\$ 140.00
23	1 pc	camera assy	\$ 150.00
			\$ 290.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Towing charges.	\$ 70.00
02		To check electrical lighting concerned.	\$ 11 50.00
03		Labour charges.	\$ 350.00
04		Putty and spray painting of the affected portion.	\$ 200.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

III Insured's Veh No : SLU5300Z
Date of Accident : 23 March 2021

Mr Yeo Cheng Chuan

Date : 26 March 2021

Estimate To Repair FBM5087A - Yamaha SNIPER T150
Chassis No : MH3UG0740H0066661

S/No	Quantity	Description	Amount
05		LABOUR & MISC. CHARGES	
		To transfer of tyre, rim and on wheel balancing.	\$ 30.00
			\$ 700.00
		Total	\$ 3,663.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: