

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 24/03/21

Address : MR KONG SIEW CHEONG
BLK 103 BUKIT PURMEI ROAD
#10-40
SINGAPORE 090103

Reference : TP 1276/03/21
Vehicle No : SLV 6756E
Make/Model : KIA CERATO K3
Insurance Co. : DIRECT ASIA

RE : QUOTATION TO SLV 6756E FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>		<u>QTY</u>	<u>AMT \$</u>
1)	REAR BUMPER <i>de</i>	1	\$ 688.00
2)	REAR BUMPER ENFORCEMENT <i>can</i>	1	\$ 313.00
3)	REAR BUMPER RETAINER <i>neu</i>	2	\$ 56.00
4)	REAR BUMPER CLIPS <i>neu</i>	10	\$ 35.00
5)	REAR BUMPER LOWER W/ REFLECTOR <i>de</i>	1	\$ 347.00
6)	BOOT COVER <i>de</i>	1	\$ 1,297.00
7)	BOOT COVER WEATHER STRIPE <i>neu</i>	1	\$ 92.00
8)	BOOT COVER LOCK <i>X SVC</i>	1	\$ 109.00 X
9)	"KIA" LOGO <i>neu</i>	1	\$ 32.00
10)	"CERATO K3" EMBLEM <i>neu</i>	1	\$ 32.00
11)	TAILLAMP OUTER <i>SCC</i>	2	\$ 708.00
12)	TAILLAMP INNER <i>can</i>	2	\$ 430.00
13)	END PANEL <i>de</i>	1	\$ 324.00
14)	END PANEL GARNISH <i>can</i>	1	\$ 66.00
15)	BOOT RELEASE CABLE <i>X SVC</i>	1	\$ 160.00 X

LIST PRICE TOTAL	\$ 4,689.00
LESS DISCOUNT 20%	\$ 937.80
LIST PRICE TOTAL AFTER LESS	\$ 3,751.20

4420
20%
3536

15)	BUMPER REVERSE SENSOR <i>at</i>	1SET	\$ 220.00
NETT PRICE TOTAL			\$220.00

200

TOTAL PARTS COST

\$3,971.20

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, BOOT COVER, TAILLAMPS AND TO PANEL BEAT BCUT & WELD END PANEL.	\$ 1,400.00	850
		(7 DAYS)	
2)	TO PUTTY & SPRAY PAINT REAR BUMPER, BOOT COVER, FENDERS, END PANEL & OTHER AFFECTED AREA.	\$ 1,000.00	800
		(5 PANELS)	
3)	TO CHECK & RECTIFY WIRING AND REPLACE SENSOR	\$ 140.00	60
4)	TUFF KOTE	\$ 320.00	80
5)	FULL COMPUTERISE WHEEL ALIGNMENT	\$ 120.00	X
LABOUR TOTAL		\$ 2,980.00	1790

TOTAL ESTIMATED REPAIR COST

\$ 6,731.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hq 20010068
6 days
45
25/03/2021
@ 1545
Repair after repair

P - 3536.00

S/N - 220.00

L - 1790.00

Suppl - 330.72

Total - 5876.72

20%
4,701.37

4,701.37 6 days

XINYA AUTO SERVICES PTE LTD

BLK 1002 BUKIT MERAH LANE 3, UNIT # 01-75, SINGAPORE 159719
E-mail : xinyaauto@singnet.com.sg

Date : 24/03/21

Address : MR KONG SIEW CHEONG
BLK 103 BUKIT PURMEI ROAD
#10-40
SINGAPORE 090103

Reference : TP 1276/03/21
Vehicle No : SLV 6756E
Make/Model : KIA CERATO K3
Insurance Co. : DIRECT ASIA

RE : SUPPLYMENTARY REPAIRS TO SGV 5104C FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>COST</u>	<u>AMT \$</u>
1) SPARE TYRE COVER <i>cmh</i> ✓	1		\$159.00
2) ENFORCEMENT BRACKET LH <i>bt</i> ✓	1		\$128.40
3) BUMPER BRACKET <i>bt</i> ✓	2		\$126.00

LIST PRICE TOTAL

\$ 413.40

LESS DISCOUNT 20%

\$ 82.68

LIST PRICE TOTAL AFTER LESS

\$ 330.72

NETT PRICE TOTAL

\$0.00

TOTAL PARTS COST

\$330.72

LABOUR AND MISCELLANEOUS CHARGES

LABOUR TOTAL

\$ -

TOTAL ESTIMATED REPAIR COST

\$ 145.20