

XINYA AUTO SERVICES PTE LTD

BLK 1002 BUKIT MERAH LANE 3, UNIT # 01-75, SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Date : 24/03/21

Address : MR KONG SIEW CHEONG
BLK 103 BUKIT PURMEI ROAD
#10-40
SINGAPORE 090103

Reference : TP 1276/03/21
Vehicle No : SLV 6756E
Make/Model : KIA CERATO K3
Insurance Co. : DIRECT ASIA

RE : SUPPLYMENTARY REPAIRS TO SGV 5104C FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>COST</u>	<u>AMT \$</u>
1) SPARE TYRE COVER <i>cmh</i> ✓	1		\$159.00
2) ENFORCEMENT BRACKET LH <i>bt</i> ✓	1		\$128.40
3) BUMPER BRACKET <i>bt</i> ✓	2		\$126.00

LIST PRICE TOTAL

\$ 413.40

LESS DISCOUNT 20%

\$ 82.68

LIST PRICE TOTAL AFTER LESS

\$ 330.72

NETT PRICE TOTAL

\$0.00

TOTAL PARTS COST

\$330.72

LABOUR AND MISCELLANEOUS CHARGES

LABOUR TOTAL

\$ -

TOTAL ESTIMATED REPAIR COST

\$ 145.20