



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0259/2021/HR
DATE : 29-Mar-21
WIP : 21436

\$9082

Justin.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/3/21
YOUR INSURED VEH NO : SMQ 3968 U

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. PHILLIPS M CONNOR
ADDRESS : 43 BLAIR ROAD
SINGAPORE 089943
TELEPHONE : HP +65 96697700
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SP2000217459-01
VEHICLE NO : SKF 7700 E
MODEL CODE : PORSCHE 911 CARRERA S COUPE 3.8
MODEL YEAR : 1/3/2012
ENGINE NO : MA103D02107
CHASSIS NO : WP0ZZZ99ZDS110697
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Mar-21
PLACE OF ACCIDENT : OUTSIDE CARPARK OF 335 SMITH STREET



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 7700 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHFR ASSY & FRONT PARKING ATD	S/N \$ 480.00	250 250.
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,350.00	500
3	TO RESPRAY FRONT BUMPER.	\$ 1,350.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,372.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 7700 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>behind</i>	1	\$ 4,500.00	✓
2	TOW EYE COVER <i>new</i>	1	\$ 54.00	+
3	RH RETAINING FRAME - BLACK <i>at end</i>	1	\$ 120.00	✓
4	FRONT BUMPER TRIM - RH <i>at new</i>	1	\$ 93.00	+
5	RETAINING STRIP - RH <i>Ne new</i>	1	\$ 66.00	+
6	FRONT BUMPER DISC - RH <i>Ne new</i> DAMAGED	1	\$ 111.00	✓
7	FRONT BUMPER FIXING <i>Ne new</i>	1	\$ 114.00	+
8	FRONT LICENCE PLATE BRACKET <i>cut</i>	1	\$ 93.00	-
9	FRONT BUMPER CENTER RETAINING FRAME <i>Ne new</i>	1	\$ 372.00	+
10	FRONT BUMPER SPOILER <i>behind</i>	1	\$ 716.00	✓
11	FRONT BUMPER SPOILER LIP <i>behind</i>	1	\$ 364.00	✓
12	FRONT PARKING AID SENSOR TRIM - RH <i>new</i>	1	\$ 45.00	+
13	PARKING AID SENSOR <i>Ne new</i>	1	\$ 424.00	+
14	FRONT BUMPER SENSOR BRACKET - RH <i>Ne new</i>	1	\$ 60.00	+
15	HEADLIGHT WASHER RETAINING PLATE - LH <i>3 for</i>	1	\$ 84.00	+
16	HEADLIGHT WASHER RETAINING PLATE - RH <i>3 for</i>	1	\$ 84.00	+
17	FRONT REINFORCEMENT BEAM <i>new</i>	1	\$ 2,069.00	+
18	FRONT BUMPER LOWER BRACKET <i>new</i>	1	\$ 633.00	+
19	FRONT WHEELHOUSE PROTECTION - RH <i>new</i>	1	\$ 465.00	+
20	ADDITIONAL HEADLIGHT - RH <i>at</i>	1	\$ 1,299.00	✓
SUB TOTAL SPARE PARTS			\$ 11,766.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 7700 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	TURN SIGNAL - RH <i>new</i>	1	\$ 213.00	+
22	HEADLIGHT WASHER JET <i>changed</i>	1	\$ 273.00	+
23	WASHER JET CLUTCH <i>rehd.</i>	1	\$ 54.00	+
24	AIR DUCT - RH <i>new</i>	1	\$ 435.00	+
25	AIR COND CONDENSER	1	\$ 1,539.00	x
26	O-RING <i>new</i>	4	\$ 36.00	x
27	SUNDRIES <i>ATC new</i>	1	\$ 300.00	+
FRONT NO. PLATE WITH HOLDER		S/N	\$ 60.00	NEC
TOTAL SPARE PARTS			\$ 14,616.00	
TOTAL LABOUR CHARGES			\$ 3,372.00	
GRAND TOTAL			\$ 17,988.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan Ling
SURVEYED DATE : 01/04/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days.

[Handwritten signature]

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT