



CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Yeo Min Si, Grace (yang Minsi, Blk 312C Sumang Link #07-157 Singapore 823312 Contact No Mobile: 91432273		Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/Yeo Min Si, Grace (yang Minsi, / 29/05/201 / 0 KNACC81CVH5075666 G4LEHS205947 KIA/NIRO 1.6 A K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	25/03/2021/ 11:01	QUD	247 / DonBong	31034		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON LOWER COVER BUMPER, BUMPER MOULDING, REPAIR LH REAR FENDER, REPAIR REAR UPPER BUMPER				420			1600.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST							60.00
E PNT98000 PAINT WORK SPRAY LH REAR FENDER, REAR BUMPER AND AFFECTED PORTION				700			1050.00
M SUNDRY PERFORM RUST PREVENTION							80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							400.00
A 34900099 RENEW REAR UNDERCARRIAGE DAMAGES							30.00
M SUNDRY LABOUR RENEW LH REAR SPORT RIM INCLUDING BALANCING							350.00
M SUNDRY SUPPLY LH REAR TIRE							120.00
A 10028901 TO CARRY OUT AFTER RADAR CALIBRATION AND SETTINGS AFTER REPAIR REAR PORTION							50.00
M SUNDRY SUNDRIES							
M MOULDING ASSY-RR BUMPER SIDE, L / CNT				1.00	20.00	00.00	20.00
M BRACKET ASSY-RR BUMPER SIDE, LH / 1 x NM				1.00	25.00	00.00	25.00
M GARNISH ASSY-QTR SIDE, LH / CNT				1.00	144.00	00.00	144.00
M COVER-RR BUMPER LWR / CNT				1.00	392.00	00.00	392.00
M WHEEL ASSY-ALUMINIUM / X NM				1.00	629.00	00.00	629.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



GST Reg No: MR-8500111-X

Reg No: 199405410K

## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
Yeo Min Si, Grace (yang Min Si, Blk 312C Sumang Link #07-157 Singapore 823312 Contact No Mobile: 91432273	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/Yeo Min Si, Grace (yang Min Si, / 29/05/201 / KNACC81CVH5075666 G4LEHS205947 KIA/NIRO 1.6 A K3R TEMPTATION RED / WK SATURN BLACK

					WIP No			
Account No	Terms	Date/Time Printed	CSE	Operator	31034			
CSM00081	Cash	25/03/2021/ 11:01	QUD	247 / DonBong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
					1.00	437.00	00.00	437.00
					1.00	117.00	00.00	117.00
M HUB & BEARING ASSY-RR			X NM		1.00	379.00	00.00	379.00
M ARM ASSY-RR TRAILING ARM, LH			X NM		1.00	90.00	00.00	90.00
M ARM COMPLETE-RR LWR, LH			X NM		1.00	108.00	00.00	108.00
M ARM ASSY-RR ASSIST			X NM		1.00	637.00	00.00	637.00
M ARM & BUSH ASSY-SUSP UPR, LH			X NM		1.00			
M CROSSMEMBER-RR			X nn					

# Estimate

SURVEYOR NAME: Steve (LKK) 00-111 111

SURVEYOR SIGNATURE: Express - ?

DATE: P/P

REMARKS: My Bel dy

5 days  
25/3/21, 2.00pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by (location) is allowed  
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Authorized signatory and company stamp

7% GST on	Nett	6,988.00	6,988.00
		489.16	489.16
	Total Payable		7,477.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.