

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

25-Mar-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 68010

1 pc	Bootlid emblem
1 pc	Bootlid CRDi
1 pc	Boot lid lower garnish
1 pc	Rear bumper
1 pc	Rear bumper lower cover
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00
1 pc	Rear bumper inner sponge
1 pc	Rear bumper reinforcement
2 pcs	Rear bumper stay o/s & n/s @ \$53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before repairs are starting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	27.00	re-
\$	29.00	re-
\$	290.00	Rp
\$	696.00	de-
\$	206.00	ab-
\$	58.00	X
\$	114.00	?
\$	607.00	?
\$	106.00	X
\$	36.00	X
\$	36.00	X
\$	92.00	o/sant
\$	2,297.00	1004
\$	229.70	
\$	2,067.30	903.60

RH Bootlid bump → re? try to polish

Less 10%

S/NETT

1 set	Rear bumper clips	\$	48.00	30.
1 set	Bootlid lower garnish clips	\$	60.00	X hn
1 set	Bootlid stickers	\$	100.00	6Dner
1 set	Reverse sensor	\$	280.00	200nm
				290.
	Sundry	\$	50.00	X un
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X nm
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, bootlid, etc	\$	850.00	200.
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$	800.00	400
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	X nm

903.60	\$	120.00	X nm
630	\$	4,675.30	630
1823.60			

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

4/5/1450, 2 days