

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 24.03.21

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLZ6505S**
MODEL : **TOYOTA PREVIA**
DATE OF ACCIDENT : 23.03.21
TIME OF ACCIDENT : 17:00HRS

JTEGDSM60A024184.
Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	CENTRE GRILLE	1	\$ 435.00	\$ 435.00
2	CENTRE GRILLE (CHROME)	1	\$ 175.00	\$ 175.00
3	CENTRE GRILLE LOGO	1	\$ 75.00	\$ 75.00
4	FRONT GRILLE TOP RUBBER	1	\$ 57.00	\$ 57.00
5	FRONT BUMPER	1	\$ 973.10	\$ 973.10
6	FRONT BUMPER FOGLAMP LH	1	\$ 295.00	\$ 295.00
7	FRONT BUMPER FOGLAMP HOUSING LH	1	\$ 125.00	\$ 125.00
8	FRONT BRACE PANEL	1	\$ 106.00	\$ 106.00
9	FRONT BUMPER LOWER GRILLE	1	\$ 150.00	\$ 150.00
10	FRONT BUMPER SIDE RETAINER	2	\$ 90.00	\$ 180.00
11	FRONT BUMPER REINFORCEMENT	1	\$ 475.00	\$ 475.00
12	FRONT BUMPER SPONGE	1	\$ 185.00	\$ 185.00
13	FRONT BUMPER UNDER COVER	1	\$ 170.00	\$ 170.00
14	HEADLAMP (HID) LH	1	\$ 1,930.00	\$ 1,930.00
15	FRONT SUPPORT PANEL	1	\$ 1,043.30	\$ 1,043.30
16	FRONT SUPPORT PANEL COVER GARNISH	1	\$ 250.00	\$ 250.00
17	RESONATOR TANK	1	\$ 294.30	\$ 294.30
18	FRONT FENDER LH	1	\$ 657.30	\$ 657.30
19	FRONT FENDER EMBLEM 'VVT-I' LH	1	\$ 38.90	\$ 38.90
20	FRONT FENDER COWLING LH	1	\$ 290.00	\$ 290.00
21	FRONT ABS SENSOR	1	\$ 397.80	\$ 397.80
22	FRONT KNUCKLE ARM LH	1	\$ 689.30	\$ 689.30
23	FRONT KNUCKLE ARM BEARING LH	1	\$ 570.00	\$ 570.00
24	FRONT LOWER ARM LH	1	\$ 687.50	\$ 687.50
25	FRONT STABILIZER BAR LINKAGE LH	1	\$ 189.30	\$ 189.30
26	FRONT SHOCK ABSORBER LH	1	\$ 458.30	\$ 458.30
27	FRONT WHEEL HUP LH	1	\$ 398.40	\$ 398.40

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLZ6505S**
 MODEL : **TOYOTA PREVIA**
 DATE OF ACCIDENT : 23.03.21
 TIME OF ACCIDENT : 17:00HRS

3568.20
 2676.15

TOTAL PRICE \$ 11,295.50
 LESS 25% \$ 2,823.88
SUB TOTAL PRICE \$ 8,471.63

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>Noc</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	ENGINE SIDE COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
3	ENGINE UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
4	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
5	FRONT FENDER COWLING CLIP LH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
6	FRONT WHEEL TYRE LH <i>new</i>	1	\$ 480.00	\$ 480.00 <i>+</i>
7	FRONT WHEEL RIM LH <i>cut</i>	1	\$ 850.00	\$ 850.00 <i>400</i>
8	POWER STEERING OIL <i>new</i>	1	\$ 250.00	\$ 250.00 <i>X</i>

460 TOTAL \$ 1,930.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>300</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>X</i>
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>X</i>
7	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>X</i>
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>X</i>
9	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>
11	RESET ABS LIGHT	\$ 350.00	<i>X</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLZ6505S**
MODEL : **TOYOTA PREVIA**
DATE OF ACCIDENT : 23.03.21
TIME OF ACCIDENT : 17:00HRS

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	---	-----------	---

TOTAL

\$4,180.00

TOTAL PARTS COST : \$ 10,401.63

TOTAL LABOUR COST : \$ 4,180.00

TOTAL REPAIR COST : \$ 14,581.63

840

Adrian G
H/S 25/03/21 -
04 days ✓

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

total: 3976.15
L/S: 3.11K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: