

CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7988D

23/03/21

MAKE :

CHIANG/QBE

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH		\$55.80
1	REAR REFLECTOR RH		\$32.00
10	REAR BUMPER CLIPS		\$22.00
1	REAR BUMPER CENTRE MOULDING		\$451.25
	SUB TOTAL		\$1,020.45
	20% 25.00%		\$255.11
	DISCOUNTED TOTAL		\$765.33
1	REVERSE SENSOR		\$180.00
			\$180.00
	Labour Charge		
	Panel Beating		\$650.00
	Spray Painting Charge		\$600.00
	Tuff Kote		\$60.00
	Towing fee		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,430.00
	ESTIMATE TOTAL		\$2,375.33

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphun 97495744
WP 24/3/21 01430

p/p Resurvey after repair, new parts
22 days
Tanphun @ Inkastron

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature