



Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: CT
 Vehicle No : SLF 5265 X
 Make & Model : MAZDA 3
 DATE: 16/3/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER <i>866.80</i>	1	\$ 1,083.00	\$ 1,083.00
2	FRONT BUMPER TOP PAD <i>285.80</i>	1	\$ 458.00	\$ 458.00
3	FRONT BUMPER TOP PAD BASE <i>185</i>	1	\$ 286.00	\$ 286.00
4	FRONT BUMPER TOWING COVER	1	\$ 45.60	\$ 45.60
5	FRONT BUMPER LOWER ABSORBER	1	\$ 308.50	\$ 308.50
6	FRONT BUMPER LOWER SUPPORT BEAN	1	\$ 215.00	\$ 215.00
7	FRONT BUMPER REINFORCEMENT <i>4545</i>	1	\$ 750.10	\$ 750.10
8	FRONT BUMPER REINFORCEMENT GARNISH <i>4119</i>	1	\$ 285.60	\$ 285.60
9	FRONT BUMPER SIDE RETAINER <i>70 RHXⁿⁿ LH de</i>	2	\$ 115.00	\$ 230.00
10	FRONT BUMPER LOWER COVER	1	\$ 189.20	\$ 189.20
11	FRONT FOG LAMP <i>218 RHXⁿⁿ LH crn</i>	1	\$ 321.00	\$ 321.00
12	FRONT FOG LAMP GARNISH <i>108 RHXⁿⁿ LH crn</i>	1	\$ 277.80	\$ 277.80
13	FRONT GRILLE <i>4560</i>	1	\$ 970.10	\$ 970.10
14	FRONT GRILLE CHROME MOULDING <i>RHXⁿⁿ LH crn</i>	2	\$ 1198.20	\$ 552.80
15	FRONT GRILLE EMBLEM	1	\$ 104.90	\$ 104.90
16	FRONT GRILLE TOP GARNISH	1	\$ 320.50	\$ 320.50
17	FRONT GRILLE SUPPORT BRACKET PIN	2	\$ 89.00	\$ 178.00
18	BONNET	1	\$ 1,120.00	\$ 1,120.00
19	BONNET SEAL	1	\$ 31.90	\$ 31.90
20	BONNET LOCK	1	\$ 208.60	\$ 208.60
21	HEADLAMP <i>1075 RHXⁿⁿ LH crn</i>	2	\$ 3,289.00	\$ 6,578.00
22	FRONT FENDER INNER SHIELD <i>RHXⁿⁿ LH crn</i>	2	\$ (115.30)	\$ 230.60
23	FRONT SUPPORT TOP PANEL	1	\$ 448.00	\$ 448.00
24	FRONT SUPPORT PANEL	1	\$ 886.90	\$ 886.90
25	RADIATOR AIR GUIDE <i>LH</i>	1	\$ 135.30	\$ 135.30
26	A/C CONDENSER	1	\$ 976.30	\$ 976.30

7	AIR INTAKE DUCT ASSY	1	\$ 188.90	\$ X UN 188.90	
28	HORN <i>w/x R4 Lhas</i>	2	\$ (96.30)	\$ 192.60	
29	WIPER WASHER TANK	1	\$ 169.30	\$ X UN 169.30	
30	RADIATOR	1	\$ 1,527.50	\$ X UN 1,527.50	
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature:</p> </div>		<i>4943</i>			
		<i>20% - 3954.40</i>			
		Subtotal :		\$	19,270.00
		Less 20%		\$	3,854.00
		Parts Total :		\$	15,416.00
NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	NUMBER PLATE	2	\$ 50.00	\$ X UN 100.00	
2	FRONT BUMPER CLIP SET	1	\$ 65.00	\$ <i>3000</i> 65.00	
3	BONNET INSULATOR CLIP SET	1	\$ 65.00	\$ X UN 65.00	
4	FRONT GRILLE CLIP SET	1	\$ 30.00	\$ <i>2000</i> 30.00	
5	FRONT FENDER INNER COWLING CLIP SET	1	\$ 78.00	\$ <i>1500</i> 78.00	
6	FRONT SUPPORT PANEL SEALANT	1	\$ 80.00	\$ X UN 80.00	
7	RADIATOR COOLANT	1	\$ 150.00	\$ X UN 150.00	
			SPECIAL NETT	\$ 568.00	
LABOUR (FRONT)				PRICE	
PANEL BEATING, REMOVAL AND REPLACING PARTS		<i>500.00</i>		\$ 1,600.00	
TO SPRAY PAINT AFFECTED AREA		<i>400.</i>		\$ 1,600.00	
DISMANTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST.				\$ X UN 150.00	
REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST				\$ X UN 150.00	
ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION				\$ <i>30.</i> 550.00	
REMOVE AND INSTALL ENGINE WIRE HARNESS. RESET ENGINE WARNING LIGHT SYSTEM WITH ON-BOARD DIAGNOSTIC COMPUTER.				\$ X UN 500.00	
<i>Tanpin 99495749</i>		<i>3954.40</i>		<i>930</i>	
<i>wp 26/3/21 @ 1130</i>		<i>65</i>			
		<i>930</i>			
			LABOUR TOTAL	\$ 4,550.00	
<i>1/5 running after repair</i>		<i>4949.40</i>			
<i>Tanpin @ 1130</i>		<i>4949.40</i>			
			Total Parts Cost	\$ 15,984.00	
			Total Labour Cost	\$ 4,550.00	
			Total Repair Cost	\$ 20,534.00	