

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JASMINE LAM LAI PENG
 BLK 643 WOODLANDS RING ROAD #04-40
 SINGAPORE 730643

Contact : 93803236

TP China
 Veron

ESTIMATE

Repair Code : CLM15211

Date in : 24/03/2021

Vehicle Num. : SLR6150Z

Model : TOYOTA C-HR HYBRID 1.8G CVT

Chassis/Eng# : ZYX102053085/2ZR8141522

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BLIND SPOT SENSOR UNIT BRACKET L/R <i>Best</i>	2	52.30	✓ 104.60
REAR BLIND SPOT SENSOR UNIT L/R <i>cracked</i>	2	1962.40	3160 ✓ 3924.80
REAR BUMPER (LOWER) <i>2 distorted</i>	1	397.60	✓ 397.60
REAR BUMPER (TOP)	1	690.00	✓ 690.00
REAR BUMPER CENTER BRACKET L/R <i>new</i>	2	51.70	X 103.40
REAR BUMPER CENTER COVER <i>del</i>	1	171.45	✓ 171.45
REAR BUMPER END SEAL COVER L/R <i>torn</i>	2	82.25	✓ 164.50
REAR BUMPER REFLECTOR GARNISH L/R <i>cut</i>	2	187.00	✓ 374.00
REAR BUMPER REFLECTOR L/R <i>RH cracked, LH cracked</i>	2	59.00	✓ 118.00
REAR BUMPER REINFORCEMENT <i>dent</i>	1	352.70	✓ 352.70
REAR BUMPER REVERSE SENSOR <i>2 pieces damaged</i>	4	392.80	502 ✓ 1571.20
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	25.40	✓ 101.60
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>trapped</i>	1	156.65	✓ 156.65
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	112.20	✓ 224.40
REAR BUMPER TOW HOOK COVER <i>del</i>	1	27.70	✓ 27.70
REAR COMPARTMENT SPONGE TRAY <i>del</i>	1	371.75	✓ 371.75
REAR END PANEL <i>Distorted</i>	1	731.35	✓ 731.35
REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	106.00	✓ 106.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JASMINE LAM LAI PENG
 BLK 643 WOODLANDS RING ROAD #04-40
 SINGAPORE 730643

Contact : 93803236

ESTIMATE

Repair Code : CLM15211

Date in : 24/03/2021

Vehicle Num. : SLR6150Z

Model : TOYOTA C-HR HYBRID 1.8G CVT

Chassis/Eng# : ZYX102053085/2ZR8141522

REAR END PANEL BRACKET L/R <i>Dented</i>	2	64.35	✓	128.70
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	347.00	✓	347.00
REAR EXHAUST SILENCER ALUMINIUM HEAT SHEILD <i>new</i>	1	271.75	+	271.75
REAR FENDER AIR VENT L/R <i>RH cracked</i>	2	73.60	<i>73.60</i>	147.20
REAR FENDER ARCH GARNISH L/R <i>cracked</i>	2	175.15	✓	350.30
REAR FENDER INNER TOP TRIM GARNISH L/R <i>at</i>	2	129.10	✓	258.20
REAR FENDER INNER TRIM GARNISH COVER L/R <i>RH Dented</i>	2	100.80	<i>100.80</i>	201.60
REAR FENDER INNER TRIM GARNISH L/R <i>cracked</i>	2	499.50	✓	999.00
REAR FLOOR SPONGE L/R <i>Dented</i>	2	209.50	✓	419.00
REAR LH BUMPER LOWER COVER <i>Dented</i>	1	189.20	✓	189.20
REAR NUMBER PLATE LAMP L/R <i>new</i>	2	50.40	+	100.80
REAR RH BUMPER LOWER COVER <i>Dented</i>	1	122.90	✓	122.90
REAR RH FENDER <i>Buckled</i>	1	943.60	✓	943.60
REAR RH TAILLAMP PANEL <i>Dented</i>	1	103.40	✓	103.40
REAR SPEAKER BOARD <i>Dented</i>	1	599.45	✓	599.45
REAR TAILGATE <i>Distorted</i>	1	1112.45	✓	1,112.45
REAR TAILGATE 'CHR' EMBLEM <i>new</i>	1	55.60	✓	55.60
REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM <i>new</i>	1	121.35	✓	121.35

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JASMINE LAM LAI PENG
 BLK 643 WOODLANDS RING ROAD #04-40
 SINGAPORE 730643

Contact : 93803236

ESTIMATE

Repair Code : CLM15211

Date in : 24/03/2021

Vehicle Num. : SLR6150Z

Model : TOYOTA C-HR HYBRID 1.8G CVT

Chassis/Eng# : ZYX102053085/2ZR8141522

REAR TAILGATE 'LOGO' EMBLEM <i>change piece</i>	1	72.20	✓	72.20
REAR TAILGATE CORNER SEAL RUBBER L/R <i>new</i>	2	47.80	+	95.60
REAR TAILGATE DAMPER L/R <i>Damaged.</i>	2	253.40	✓	506.80
REAR TAILGATE GASKET SEAL L/R <i>new</i>	2	6.60	+	13.20
REAR TAILGATE HINGES L/R	2	75.30	+	150.60
REAR TAILGATE INNER SIDE GARNISH L/R <i>cut</i>	2	115.30	✓	230.60
REAR TAILGATE INNER TOP GARNISH <i>cut</i>	1	151.10	✓	151.10
REAR TAILGATE INNER TRIM GARNISH <i>cracked</i>	1	324.15	✓	324.15
REAR TAILGATE LOWER RUBBER STOPPER L/R <i>new</i>	2	32.00	+	64.00
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	467.60	389 ✓	467.60
REAR TAILGATE MECHANISM LOCK COVER <i>Delid</i>	1	43.30	✓	43.30
REAR TAILGATE MECHANISM LOCK STRIKER <i>Best</i>	1	40.40	✓	40.40
REAR TAILGATE OPENER BUTTON SENSOR <i>new</i>	1	179.10	+	179.10
REAR TAILGATE OUTER GARNISH <i>cracked</i>	1	925.60	882 ✓	925.60
REAR TAILGATE OUTER GARNISH FASTER CLIPS <i>new</i>	5	11.10	20 ✓	55.50
REAR TAILGATE REFLECTOR L/R <i>cracked</i>	2	506.70	✓	1,013.40
REAR TAILGATE SPOILER <i>cracked</i>	1	3655.10	1200 (500) ✓	3,655.10
REAR TAILGATE THIRD BRAKE LAMP <i>cut</i>	1	353.00	✓	353.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JASMINE LAM LAI PENG
 BLK 643 WOODLANDS RING ROAD #04-40
 SINGAPORE 730643

Contact : 93803236

ESTIMATE

Repair Code : CLM15211

Date in : 24/03/2021

Vehicle Num. : SLR6150Z

Model : TOYOTA C-HR HYBRID 1.8G CVT

Chassis/Eng# : ZYX102053085/2ZR8141522

REAR TAILGATE WEATHER STRIP <i>lt</i>	1	371.00	✓	371.00
REAR TAILGATE WINDSCREEN GLASS <i>shattered</i>	1	1340.00	✓	1,340.00
REAR TAILGATE WINDSCREEN LOWER MOULDING <i>3 per</i>	1	68.20	✓	68.20
REAR TAILGATE WINDSCREEN SIDE MOULDING L/R	2	44.80	✓	89.60
REAR TAILGATE WIPER ARM <i>Disbled</i>	1	93.40	✓	93.40
REAR TAILGATE WIPER ARM COVER <i>missing</i>	1	16.70	✓	16.70
REAR TAILGATE WIPER BLADE <i>lt</i>	1	46.50	✓	46.50
REAR TAILGATE WIPER MOTOR <i>Dead</i>	1	827.40	✓	827.40
REAR TAILLAMP L/R <i>could</i>	2	768.10	✓	1,536.20
REAR TAILLAMP LOWER BRACKET L/R <i>Dead</i>	2	56.85	✓	113.70
REAR TAILLAMP SIDE COVER L/R <i>lt</i>	2	72.70	✓	145.40

Subtotal before discount

29,152.55

Percentage discount 25%

7,288.14

Sub-total 1

21,864.41

REAR BUMPER CLIPS - SET <i>lt</i>	1	50.00	30	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>lt</i>	1	40.00	20	40.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET <i>lt</i>	2	40.00	40	80.00
REAR FENDER INNER TOP TRIM GARNISH CLIPS L/R - SET <i>lt</i>	2	30.00	✓	60.00

*** This is a computer-generated document which requires no signature.***

page 4

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JASMINE LAM LAI PENG
 BLK 643 WOODLANDS RING ROAD #04-40
 SINGAPORE 730643

Contact : 93803236

ESTIMATE

Repair Code : CLM15211

Date in : 24/03/2021

Vehicle Num. : SLR6150Z

Model : TOYOTA C-HR HYBRID 1.8G CVT

Chassis/Eng# : ZYX102053085/2ZR8141522

REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>me</i>	2	50.00	<i>60</i> 100.00
REAR NUMBER PLATE <i>Bent</i>	1	25.00	<i>✓</i> 25.00
REAR NUMBER PLATE HOLDER <i>Del</i>	1	50.00	<i>30</i> 50.00
REAR SPARE TYRE PANEL INSULATOR MAT <i>me</i>	1	250.00	<i>20</i> 250.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>me</i>	1	80.00	<i>30</i> 80.00
REAR TAILGATE REVERSE CAMERA <i>Damaged</i>	1	500.00	<i>380</i> 500.00
REAR TAILGATE SPOILER CLIPS - SET <i>me</i>	1	50.00	<i>30</i> 50.00
REAR TAILGATE WINDSCREEN GLASS SEALANT <i>me</i>	1	60.00	<i>✓</i> 60.00
REAR TAILGATE WINDSCREEN SEALANT <i>Replaced</i>	1	80.00	<i>+</i> 80.00
REAR TAILLAMP CLIPS L/R - SET <i>New</i>	2	30.00	<i>20</i> 60.00
Subtotal before discount			1,485.00
Percentage discount 0%			0.00
Sub-total 2			1,485.00
Parts-total			23,349.41

LABOUR

To reset system after repair works

+ 280.00

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

✓ 80.00

To remove, reinstall tailgate windscreen

120 ~~150.00~~

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80 ~~150.00~~

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

JASMINE LAM LAI PENG

BLK 643 WOODLANDS RING ROAD #04-40

SINGAPORE 730643

Contact : 93803236

ESTIMATE

Repair Code : CLM15211

Date in : 24/03/2021

Vehicle Num. : SLR6150Z

Model : TOYOTA C-HR HYBRID 1.8G CVT

Chassis/Eng# : ZYX102053085/2ZR8141522

To send vehicle for cleaning, shampoo, upholstery and cushion seat.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and reinstall exhaust pipe.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

80 180.00
 1500 2,000.00
 X 100.00
 1500 2,100.00
 ✓ 100.00
 ✓ 80.00

3540

Labour Total**5,220.00****Parts & Labour Total****28,569.41**

*** This is a computer-generated document which requires no signature.***

page 6

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
 2/s 26/03/21

10 Days

total: 22488.40

h/s: 18K

18K