

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

✉ zoomautowerks@gmail.com

Car Number: SJC1819P

Model : Honda Fit

Damaged Area: **(Rear Damaged)**

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

1	Tailgate	\$ 1,408.40
2	Tailgate inner trim board	\$ 496.10
3	Tailgate weatherstrip	\$ 299.80
4	Tailgate inner lock	\$ 286.40
5	Tailgate damper @ SGD 231.10	\$ 462.20
6	Tailgate windscreen glass	\$ 1,290.30
7	Tailgate windscreen moulding	\$ 152.80
8	Tailgate emblem "H"	\$ 95.00
9	Tailgate emblem "FIT"	\$ 75.00
10	Tailgate outer garnish	\$ 256.60
11	Tailgate wiper arm	\$ 215.40
12	Tailgate wiper motor	\$ 386.50
13	Tailgate wiper blade	\$ 42.80
14	Taillamp assy @ SGD 423.40	\$ 846.80
15	Taillamp panel @ SGD 225.80	\$ 451.60
16	Rear bumper	\$ 856.40
17	Rear bumper side retainer @ SGD 120.20	\$ 240.40
18	Rear bumper bracket @ SGD 68.20	\$ 136.40
19	Rear bumper tow cover	\$ 48.00
20	Rear spare tyre top board	\$ 275.40
21	Rear spare tyre top foam	\$ 295.20
22	Rear spare tyre panel	\$ 937.10
23	Rear fender inner trim garnish @ SGD 463.20	\$ 926.40
24	Rear fender n/s	\$ 1,614.00
25	Rear end panel	\$ 765.50
26	Rear end panel top garnish	\$ 428.30
27	Rear exhaust box	\$ 980.00
28	Rear exhaust muffler	\$ 180.00
29	Rear exhaust mounting @ \$68.00	\$ 204.00

Parts : \$ 14,652.80**Less Parts 20% : \$ 2,930.56****Total Parts : \$ 11,722.24**

Special Net Items :

Rear End Panel Sealant	\$ 80.00
Rear Fender Sealant	\$ 80.00
Rear Tailgate Glass Sealant	\$ 80.00
Rear Exhaust Chrome Muffler	\$ 280.00
Rear Number Plate W/Garnish	\$ 68.00
Reverse Sensor	\$ 280.00
Total S/N Parts :	\$ 868.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$ 1,400.00
To Putty, Spray Paint on Affected Accident Areas	\$ 1,400.00
To Check & Re-Connect all electrical wiring	\$ 50.00
To Remove & Install Rear Tailgate Components Trim & Garnish	\$ 150.00
To Remove & Install Rear Spare Tyre Components, Trim & Garnish	\$ 150.00
To Remove & Install Rear Tailgate Glass	\$ 150.00
To Re-Position, Drill & Install Reverse Sensor	\$ 150.00
To Conduct Water Leakage Test	\$ 150.00
To Rust Proof Affected Areas	\$ 200.00
Total Labour :	\$ 3,800.00

TOTAL PARTS : \$ 11,722.24

TOTAL SPECIAL NET IT \$ 868.00

TOTAL LABOUR : \$ 3,800.00

TOTAL REPAIR COST : \$ 16,390.24

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :