



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 37971

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#18-00 / 19-00

THE OCTAGON

S'PORE 069534

ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

DATE : 24/03/2021

CLAIM NO. : 11698

POLICY NO. : PNMCM2020-00004428

FROM : HASRIANAH

VEHICLE NO. : FBN5742L

MAKE/MODEL : YAM / AEROX

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL / BT P/N: 66786 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 ✓
2	BALL RACE 2 / MC. P/N: 50623 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00 ✓
3	BAR HANDLE / QT P/N: 68355 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00 ✓
4	BEARING, STEERING UPPER / MC. P/N: 62411 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 ✓
5	BOARD, FOOTREST 2 / BT. / CMA P/N: 67090 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00 ✓
6	BRACKET HEAD LIGHT / BT. P/N: 68344 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 ✓
7	BRACKET HEAD LIGHT / BT. P/N: 68332 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 ✓
8	CALIPER BRAKE (NISSIN) SAMURAI WITH BRACKET / BT. - (REPORTED BY MECHANIC)	REPLACE	1.00	\$518.00	518.00 ✓
9	COVER FRONT (BLACK) / BR. - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00 ✓

*37971 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 9001: 2015

Quotation Nos. : 37971

S/N	Description	Action	Qty	Unit Price	Amount
26	HEADLAMP ASSY <i>✓ cat</i> P/N: 68946 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$385.00 ✓	385.00
27	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$63.00 <i>360 ✓</i>	504.00
28	LEVER CLUTCH <i>✓ cat</i> P/N: 68930 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00 ✓	16.00
29	MID RACE BALL <i>✓ msc</i> P/N: 18578 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00 ✓	13.00
30	MUDGUARD FRONT (WHITE) <i>✓ cat</i> - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00 ✓	38.00
31	MUDGUARD FRONT INNER <i>✓ cat</i> P/N: 66782 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00 ✓	13.00
32	PLATE DISC BRAKE FRONT <i>✓ BT</i> P/N: 58182 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$75.00 ✓	75.00
33	PLATE NUMBER FRONT (STRAIGHT) <i>✓ cat</i> P/N: 26249 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00 ✓	21.00
34	PROTECTOR MUFFLER <i>✓ cat</i> P/N: 67089 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00 ✓	31.00
35	RETAINER BALL BEARING <i>✓ msc</i> P/N: 57083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00 ✓	16.00
36	RIVET <i>✓ msc</i> P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	7.00	\$3.00 ✓	21.00
37	SIGNAL FRONT ASSY RH <i>✓ R's</i> P/N: 68368 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00 ✓	16.00
38	STICKER <i>✓</i> P/N: 68367 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00 ✓	9.00
39	STICKER ABS <i>✓ msc</i> - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00 ✓	12.00
40	TRANSPORT CHARGES <i>✓</i> P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00 <i>45 ✓</i>	56.00

SUB TOTAL
GST @ 7 %\$2,928.00
\$204.96

*37971 *

bizSAFE



Quotation Nos. : 37971

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL (SGD)					\$3,132.96

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

3 Days.

P/P

After repair photos.

Emo Qiong - LKK

8288 0282

26/3/21

2368

-10%: 2131.2

2536.2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*37971

*

bizSAFE

