

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong

Date: 10 Aug 2021

**Preliminary Advice**

Insured Vehicle No	: GW3794T	Accident Date	: 19/03/2021
TP Vehicle No	: GBL580E	Assignment Date	: 25/03/2021
Make	: TOYOTA HIACE	Est. Duration of Repair	: 5
Date of Inspection	: 26/3/21		
Inspection At	: J-MART MOTOR PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,291.92
Revised Amount	:S\$	4,339.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,339.00
Lump Sum Repair	:S\$	3,450.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair

- ( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .