

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/21003909/U9f3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LIA \$37439 De 79500

21/4/14 2/5 & 3500 confirmed with Alfred (Red &)

21/4/14 @ 4.11pm revised to Alfred Toh via Meinman.

Date/Time, File Pass to?

1) 21/4/14

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

MER-TP

3500

EURO SUCCESS SERV PTE. LTD
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: SMN4677T Model: HONDA CIVIC

Not Authorized
25/3/21
2/s \$3500
Tel: 98289277
H. Huat

QTY	List Items	Price \$	
1	REAR BOOT LID <i>surf/waxed</i>	687 750.00	✓
1	REAR BOOT EMBLEM 'CIVIC' <i>11</i>	38.60	X
1	REAR BOOT EMBLEM 'LOGO' <i>11</i>	32.70	✓
1	REAR BOOT EMBLEM 'I-VTEC' <i>11</i>	38.60	✓
2	REAR BOOT LAMPS L-R @450 <i>11</i>	900.00	X
1	REAR BOOT CHROME MOULDING <i>11</i>	126.10	X
2	REAR BOOT LICENCE LAMPS @42.2 <i>11</i>	84.40	X
1	REAR BOOT INNER TRIM <i>11</i>	350.00	X
10	REAR BOOT INNER TRIM CLIPS@4.5 <i>11</i>	45.00	X
1	REAR BOOT INNER LOCK <i>surf</i>	145.80 220.00	✓
1	REAR BOOT INNER LOCK STRIKER <i>11</i>	28.60	X
1	REAR BOOT INNER PULL POCKET <i>11</i>	89.60	X
1	REAR BOOT W/ STRIP <i>11</i>	91.90	✓
2	REAR BOOT HINGES L-R @66.9 <i>11</i>	133.80	X
2	REAR BOOT STOPPER @12.2 <i>11</i>	24.40	X
1	REAR BUMPER <i>11</i>	579.90 850.00	✓
2	REAR BUMPER REFLECTOR <i>grille</i>	MS 75.00 173.20	✓
2	REAR BUMPER SIDE RETAINER L-R @48.2 <i>11</i>	96.40	60
10/set	REAR BUMPER CLIP @4.5 <i>11</i>	27.00	✓
1	REAR END PANEL <i>11</i>	265.70 750.00	✓
1	REAR END PANEL GARNISH <i>11</i>	50.30 126.20	✓
1	REAR bumper reinforcement <i>11</i>	180 450.00	✓
1	REAR FLOOR PANEL <i>11</i>	711.60	X
2	REAR FLOOR PANEL SIDE EXTENSIONS @185 <i>11</i>	370.00	X
2	REAR FENDER L-R @841.6 <i>11</i>	1683.20	X
2	REAR FENDER INNER TRIMS L-R @242.6 <i>11</i>	485.20	X
10	REAR FENDER INNER TRIM CLIPS @4.5 <i>11</i>	45.00	X
2	REAR FENDER INNER SHIELD L-R @58.6 <i>11</i>	117.20	X
1	REAR SPARE WHEEL RETAINER LOCK <i>11</i>	48.60	X
2	REAR TAILLAMP L-R @650 <i>one</i>	285.50 x 2 = 571 1300.00	✓
2	REAR TAILLAMP PANEL L-R @155.1 <i>11</i>	310.20	X
2	REAR TAILLAMP LOWER BRACKET @18.9 <i>11</i>	37.80	X
1	REAR EXHAUST SILENCER <i>11</i>	1150.00	X
1	REAR EXHAUST INSULATOR <i>11</i>	120.20	X
2	REAR EXHAUST MOUNTING @22.1 <i>11</i>	44.20	X
1 SET	REAR WINDSCREEN MOULDING <i>11</i>	89.90	X
TOTAL		\$11,939.60	
LESS 20%		\$2,387.92	
TOTAL		\$9,551.68	

Special Nett Items

1	REAR WINDSCREEN SEALANT	11	100.00	X
1	REAR NO PLATE	11	80.00	X
1 set	REAR REVERSE SENSOR	shell	350.00	200
1	REAR REVERSE CAMERA	11	450.00	X

\$980.00

Labour Charges

TOWING CHARGES	11	100.00	X
TO CHECK REAR ELECTRICAL WIRING		150.00	30
TO REMOVE , REFIX REAR WINDSCREEN	11	180.00	X
TO REMOVE , REFIX R/INTERIOR TRIMS TO ASSIST REPAIR		150.00	80
TO REMOVE , REFIX REVERSE SENSOR AND CAMERA		80.00	50
TO REMOVE , REFIX EXHAUST	11	120.00	X
TO RESPRAY UNDERCOATING		500.00	60
TO RESPRAY PAINTING ETC		2500.00	980
PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS		3000.00	800

\$6,780.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$17,311.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2766
20%

P- 2212.80

S.N- 2000.00

L- 2000.00

4412.80

20%

3530