

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 22.03.2021
 Emailed : 28.04.2021, 1.20pm
 Date Survey : 25.03.2021

VEHICLE NO : SMP 1825 S
 MODEL : KIA CERATO 1.6 A GT
 WIP : 30926

Material	:	\$	8,839.20
Labour	:	\$	8,440.00
Sub-Total	:	\$	17,279.20
	:	\$	-
Less Excess	:	\$	-
Total	:	\$	17,279.20
GST 7%	:	\$	1,209.54
Grand Total	:	\$	18,488.74
Finalise By/Date	:		LOI / 28/04/2021

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NTUC INCOME INS CO-OPERATIVE LTD	Cust No/Name LCV11003/YEO CHOK LIH
ATTN: MOTOR CLAIMS DEPARTMENT	Reg No/Reg Date SMP1825S / 02/09/2019
73 BRAS BASAH ROAD #05-01	Date In/Mileage 25/03/2021/ 19583
NTUC TRADE UNION HOUSE	Chassis/Package KNAF5416MK5052969 /KC17P
SINGAPORE 189556	Engine No G4FGKH749566
Contact No 6-510 2040	Make/Model KIA/CERATO 1.6 A GT LINE H171
25/03/2021	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
RNX00002	Credit	28/04/2021/ 12:17	BLC	260 / AiTing	30926
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000 REPLACE DAMAGED APRTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 400.00
E PNT88000 REMOVE & INSTALL FRONT PARKING SENSOR TO FACILITATE REPAIR					✓ 60.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM					✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE					✓ 120.00
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, BOOT LID, REAR END PANEL, REPAIR RH REAR FENDER, RH REAR CHASSIS, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 1200.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS TO FACILITATE REPAIR					? 300.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR					✓ 60.00
E PNT88000 REMOVE & INSTALL CARPET AND REAR SEATS TO FACILITATE REPAIR					? 300.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT LID, REAR END PANEL, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME					✓ 1400.00
E PNT88000 REMOVE & INSTALL REAR SPOILER TO FACILITATE REPAIR					✓ 80.00
M SUNDRY APPLY SEALANT ON AFFECTED PORTIONS					✓ 40.00
M SUNDRY SUPPLY C&C LOGO					✓ 40.00
A 90000001 REMOVE & REINSTALL REAR EXHAUS PIPE TO FACILITATE REPAIR					✓ 300.00
M SUNDRY SUNDRIES					✓ 20.00
E PNT98000					✓ 350.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NTUC INCOME INS CO-OPERATIVE LTD	Cust No/Name LCV11003/YEO CHOK LIH
ATTN: MOTOR CLAIMS DEPARTMENT	Reg No/Reg Date SMP1825S / 02/09/2019
73 BRAS BASAH ROAD #05-01	Date In/Mileage 25/03/2021/ 19583
NTUC TRADE UNION HOUSE	Chassis/Package KNAF5416MK5052969 /KC17P
SINGAPORE 189556	Engine No G4FGKH749566
Contact No 6-510 2040	Make/Model KIA/CERATO 1.6 A GT LINE H171
25/03/2021	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
RNX00002	Credit	28/04/2021/ 12:17	BLC	260 / AiTing	30926			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
RESPRAY ON FRONT BUMPER								✓ 50.00
S SPECIALISTJOB								
SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								120.00
E PNT88000								
REMOVE & INSTALL LH REAR QUARTER GLASS AND CONDUCT WATER LEAK TEST → Supp.								240.00
E PNT88000								
REMOVE & INSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST → Supp.								80.00
M SUNDRY								
SUPPLY REAR WINDSCREEN GLASS SEALANT → Supp.								✓ 2000.00
E PNT88000								
REPLACE DAMAGED PARTS, REPLACE LH REAR FENDER, REAR FLOOR PANEL, REPAIR LH & RH REAR LAMP HOUSING, RH REAR CHASSIS → Supp.								✓ 1050.00
E PNT98000								
RESPRAY ON RH REAR FENDER, REAR FLOOR PANEL, REPAIR LH & RH REAR LAMP HOUSING, RH REAR CHASSIS → Supp.								200.00
A 90000001								
REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR → Supp.								
X	COVER-FR BUMPER				1.00	✓ 633.00	20.00	506.40
X	COVER-FR BUMPER FOG LAMP,LH				1.00	✓ 15.00	20.00	12.00
X	LAMP ASSY-SIDE REPEATER,LH				1.00	✓ 143.00	20.00	114.40
X	ULTRASONIC SENSOR ASSY-P.A.S				1.00	✓ 163.00	20.00	130.40
X	ORNAMENT-KIA NO.115				1.00	✓ 32.00	20.00	25.60
X	COVER-RR BUMPER				1.00	✓ 651.00	20.00	520.80
X	COVER-RR BUMPER LWR				1.00	✓ 241.00	20.00	192.80
X	COVER-RR BUMPER FOG LAMP,LH				1.00	✓ 19.00	20.00	15.20
X	BEAM-RR BUMPER				1.00	✓ 318.00	20.00	254.40
X	PANEL ASSY-TRUNK LID				1.00	✓ 1297.00	20.00	1037.60
X	PANEL ASSY-BACK				1.00	✓ 324.00	20.00	259.20
X	LOGO ASSY-KIA SUB				1.00	✓ 32.00	20.00	25.60
X	EMBLEM-CERATO				1.00	✓ 28.00	20.00	22.40
X	EMBLEM-GT LINE				1.00	✓ 45.00	20.00	36.00
X	LAMP ASSY-REAR COMB OUTSIDE,LH				1.00	✓ 675.00	20.00	540.00
X	PROTECTOR-HEAT REAR				1.00	✓ 136.00	20.00	108.80

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NTUC INCOME INS CO-OPERATIVE LTD	Cust No/Name LCV11003/YEO CHOK LIH
ATTN: MOTOR CLAIMS DEPARTMENT	Reg No/Reg Date SMP1825S / 02/09/2019
73 BRAS BASAH ROAD #05-01	Date In/Mileage 25/03/2021/ 19583
NTUC TRADE UNION HOUSE	Chassis/Package KNAF5416MK5052969 /KC17P
SINGAPORE 189556	Engine No G4FGKH749566
Contact No 6-510 2040	Make/Model KIA/CERATO 1.6 A GT LINE H171
25/03/2021	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
RNX00002	Credit	28/04/2021/ 12:17	BLC	260 / AiTing	30926			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	GRILLE-FRONT BUMPER				1.00	485.00	20.00	388.00
X	MOULDING-FRONT BUMPER,LH				1.00	216.00	20.00	172.80
X	ABSORBER-FRONT BUMPER ENERGY				1.00	84.00	20.00	67.20
X	WIRING ASSY-BUMPER EXTENSION	→ Supp.			1.00	207.00	20.00	165.60
X	COVER-RR BUMPER FOG LAMP,RH				1.00	19.00	20.00	15.20
X	LAMP ASSY-SIDE T/SIGNAL,LH				1.00	181.00	20.00	144.80
X	LAMP ASSY-SIDE T/SIGNAL,RH				1.00	181.00	20.00	144.80
X	EXTN WIRING ASSY-BWS				1.00	207.00	20.00	165.60
X	BRACKET-RR BEAM UPR MTG,RH				1.00	9.00	20.00	7.20
X	BRACKET-RR BEAM LWR,CTR				1.00	6.00	20.00	4.80
X	BRACKET-RR BEAM LWR MTG				2.00	6.00	20.00	9.60
X	STAY-RR BUMPER LH				1.00	65.00	20.00	52.00
X	STAY-RR BUMPER RH				1.00	65.00	20.00	52.00
X	BRACKET-ASSY RR BPR SIDE UPR,R				1.00	31.00	20.00	24.80
X	MAT ASSY-LUGGAGE COVERING				1.00	211.00	20.00	168.80
X	TRIM ASSY-RR TRANSVERSE				1.00	41.00	20.00	32.80
X	W/STRIP-TRUNK LID OPNG				1.00	100.00	20.00	80.00
X	LATCH ASSY-TRUNK LID				1.00	112.00	20.00	89.60
X	PANEL ASSY-REAR FLOOR,RR				1.00	219.00	20.00	175.20
X	REINF-RR SPARE TIRE WELL CROSS				1.00	41.00	20.00	32.80
X	HOOK-TOWING				1.00	16.00	20.00	12.80
X	REINF-TOWING HOOK				1.00	14.00	20.00	11.20
X	PANEL ASSY-QUARTER OUTER,LH				1.00	1349.00	20.00	1079.20
X	PANEL ASSY-RR COMB LAMP HSG,LH				1.00	139.00	20.00	111.20
X	PANEL ASSY-RR COMB LAMP HSG,RH				1.00	135.00	20.00	108.00
X	LAMP ASSY-REAR COMB INSIDE,LH				1.00	608.00	20.00	486.40
X	LAMP ASSY-REAR COMB INSIDE,RH				1.00	608.00	20.00	486.40
X	LAMP ASSY-REAR COMB OUTSIDE,RH				1.00	675.00	20.00	540.00
X	CLIP				15.00	1.00	20.00	12.00
X	FASTENER				5.00	1.00	20.00	4.00
X	GROMMET ASSY-SCREW				2.00	2.00	20.00	3.20
X	SILENCER,FLOOR				2.00	13.00	20.00	20.80
X	COVER-RR BUMPER UNDER,LH				1.00	33.00	20.00	26.40

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NTUC INCOME INS CO-OPERATIVE LTD	Cust No/Name LCV11003/YEO CHOK LIH
ATTN: MOTOR CLAIMS DEPARTMENT	Reg No/Reg Date SMP1825S / 02/09/2019
73 BRAS BASAH ROAD #05-01	Date In/Mileage 25/03/2021/ 19583
NTUC TRADE UNION HOUSE	Chassis/Package KNAF5416MK5052969 /KC17P
SINGAPORE 189556	Engine No G4FGKH749566
Contact No 6-510 2040	Make/Model KIA/CERATO 1.6 A GT LINE H171
25/03/2021	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
RNX00002	Credit	28/04/2021/ 12:17	BLC	260 / AiTing	30926

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	130.40
X BRACKET ASSY-SPARE TIRE MTG	1.00	15.00	20.00	12.00
Z TEXT				
AIG OD CLAIM.				
DOA : 22.03.21				
SURVEYOR STEVE LKK 25.03.21				
POLICY NO : 1900151806				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	8,839.20	Nett	17,279.20
Labour	8,210.00	7% GST on	1209.54
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	18,488.74
Diagnostics Job	0.00		
Sundry/Others	180.00		
Total(w/o GST)	17,279.20		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO.: **AIG**


Supplementary Parts For Registration No.: **SMP 1825 S**

	<u>Materials</u>	<u>Cost (\$)</u>	
1	Wiring assy-bumper extension	207.00	✓ BR
2	Reinf-RR spare tire well cross	41.00	✓ nec
3	Hook-towing	16.00	✓ nec
4	Reinf-towing hook	14.00	✓ nec
5	Panel assy-Quarter outer, LH	1,349.00	✓ DG
6	Panel assy-RR comb lamp hsg, LH	139.00	✓ DB
7	Panel assy-RR comb lamp hsg, RH	135.00	✓ DB
8	Clips (x15)	15.00	✓ nec
9	Fastener (x5)	5.00	✓ nec
10	Grommets (x2)	4.00	✓ nec
11	Silencer, floor (x2)	26.00	✓ nec
12	Cover-RR bumper under, LH	33.00	✓ BR
13	Ultrasonic sensor assy-BWS	163.00	✓ BR
14	Bracket assy-spare tire mtg	15.00	✓ nec
Total Materials		2,162.00	
Less 20% discount		432.40	
Total after discount		1,729.60	

	<u>Labour</u>	<u>Cost (\$)</u>	
1	Remove & install LH rear quarter glass and conduct water leak test	120.00	✓
2	Remove & install rear windscreen glass and conduct water leak test	240.00	✓
3	Supply rer windscreen glass sealant	80.00	✓
4	Replace damaged parts, replace LH rear fender, rear floor panel, LH & RH rear comb lamp housing, RH rear chassis	2000 1,000.00	✓
5	Respray on RH rear fender, Rear floor panel, Repair LH & RH rear comb lamp housing, RH rear chassis	1,050.00	✓
6	Remove & install fuel tank to facilitate repair	200.00	✓
Total labour		2,690.00	
Total amount		4,410.00 5419.60	
7% GST		309.37	
Grand total		<u>\$ 4,728.97</u>	

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
 DID : 6568 4556 / 6568 4501
 FAX : 6567 5258 / 6565 1240



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Save All DTC

Save



ICU



CLU



WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0244

VCI Ver.

02.52

ECU Ver.

M-E-K-01-00-0185

OS Ver.

Android 10