



CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| YEO CHOK LIH<br>BLK 593B MONTREAL LINK<br>#15-56<br>SINGAPORE 752593<br>Contact No | Cust No/Name LCV11003/YEO CHOK LIH<br>Reg No/Reg Date SMP18255 / 02/09/201<br>Date In/Mileage / 0<br>Chassis No KNAF5416MK5052969<br>Engine No G4FGKH749566<br>Make/Model KIA/CERATO 1.6 A GT LINE H171<br>Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK |

| Account No                             | Terms  | Date/Time Printed | CSE | Operator     | WIP No |            |       |             |
|--|--|-------------------|-----|--------------|--------|------------|-------|-------------|
| LCV11003                               | CRDVCH   | 25/03/2021/ 13:30 |     | 442 / CocoLu | 30926  |            |       |             |
| Description of Goods / Services        |  |                   |     |              | Qty    | Unit Price | Disc% | Amount      |
| E PNT88000                             | RENEW FRT BUMPER   | 400 X 1           |     |              |        |            |       | 400.00      |
| M SUNDRY                               | SPRAY PAINT FOR FRT BUMPER   | 350 X 1           |     |              |        |            |       | 350 20.00   |
| E PNT88000                             | REMOVE & INSTALL FRT PARKING SENSOR                                    |                   |     |              |        |            |       | 60.00       |
| M SUNDRY                               | FRT NUMBER PLATE WITH FRAME  |                   |     |              |        |            |       | 50.00       |
| A 90000001                             | CHECK WIRING & ELECTRICAL SYSTEM                                       |                   |     |              |        |            |       | 30.00       |
| A 10028901                             | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST                   |                   |     |              |        |            |       | 120.00      |
| E PNT88000                             | SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT | 3 X 400           |     |              |        |            |       | 4000.00     |
| E PNT88000                             | REPAIR REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH |                   |     |              |        |            |       | 1200 300.00 |
| E PNT88000                             | REMOVE & INSTALL REAR COMPARTMENT TRIMS                                |                   |     |              |        |            |       | 60.00       |
| E PNT88000                             | REMOVE & INSTALL PARKING SENSOR  |                   |     |              |        |            |       | 300.00      |
| E PNT88000                             | REMOVE & INSTALL CARPAT AND REAR SEATS                                 |                   |     |              |        |            |       | 3500.00     |
| E PNT98000                             | SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT | 4 X 350           |     |              |        |            |       | 1400 100.00 |
| E PNT88000                             | REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH        |                   |     |              |        |            |       | 80 120.00   |
| E PNT88000                             | REMOVE & INSTALL REA SPOILER   |                   |     |              |        |            |       | 40 50.00    |
| M SUNDRY                               | APPLY SEALANT FOR ACCIDENT PORTION                                     |                   |     |              |        |            |       | 40.00       |
| M SUNDRY                               | REAR NUMBER PLATE WITH FRAME   |                   |     |              |        |            |       |             |
| M SUNDRY                               | C&C LOGO   |                   |     |              |        |            |       |             |
| Confirm & accepted by                  |  |                   |     |              |        |            |       |             |
| Authorized signatory and company stamp |  |                   |     |              |        |            |       |             |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| YEO CHOK LIH<br><br>BLK 593B MONTREAL LINK<br>#15-56<br>SINGAPORE 752593<br><br>Contact No | Cust No/Name LCV11003/YEO CHOK LIH<br>Reg No/Reg Date SMP1825S / 02/09/201<br>Date In/Mileage / 0<br>Chassis No KNAF5416MK5052969<br>Engine No G4FGKH749566<br>Make/Model KIA/CERATO 1.6 A GT LINE H171<br>Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK |

| Account No                          | Terms                           | Date/Time Printed | CSE | Operator     | WIP No |            |       |        |
|-------------------------------------|---------------------------------|-------------------|-----|--------------|--------|------------|-------|--------|
| LCV11003                            | CRDVCH                          | 25/03/2021/ 13:30 |     | 442 / CocoLu | 30926  |            |       |        |
| Description of Goods / Services     |                                 |                   |     |              | Qty    | Unit Price | Disc% | Amount |
| E PNT88000                          |                                 |                   |     |              |        |            |       | 500.00 |
| TO STRAIGHTEN REAR BOTH CHASSIS     |                                 |                   |     |              |        |            |       |        |
| A 90000001                          |                                 |                   |     |              |        |            |       | 300.00 |
| RENEW REAR EXHAUST SYSTEM (C R b R) |                                 |                   |     |              |        |            |       | 20.00  |
| M SUNDRY                            |                                 |                   |     |              |        |            |       |        |
| Sundry                              |                                 |                   |     |              |        |            |       |        |
| M                                   | COVER-FR BUMPER                 | / CRU ? / OR      |     |              | 1.00   | 633.00     | 00.00 | 633.00 |
| M                                   | GRILLE-FRONT BUMPER             |                   |     |              | 1.00   | 485.00     | 00.00 | 485.00 |
| M                                   | COVER-FR BUMPER FOG LAMP, LH    | / CUT             |     |              | 1.00   | 15.00      | 00.00 | 15.00  |
| M                                   | LAMP ASSY-FRONT FOG, LH         | X NAI             |     |              | 1.00   | 303.00     | 00.00 | 303.00 |
| M                                   | MOULDING-FRONT BUMPER, LH       | X NAI / CUT       |     |              | 1.00   | 216.00     | 00.00 | 216.00 |
| M                                   | LAMP ASSY-SIDE REPEATER, LH     | / CUT             |     |              | 1.00   | 143.00     | 00.00 | 143.00 |
| M                                   | ABSORBER-FRONT BUMPER ENERGY    | / OR              |     |              | 1.00   | 84.00      | 00.00 | 84.00  |
| M                                   | BRACKET-FR BUMPER UPR SIDE MTG  | / X NAI           |     |              | 1.00   | 22.00      | 00.00 | 22.00  |
| M                                   | ULTRASONIC SENSOR ASSY-P.A.S    | / OR              |     |              | 1.00   | 163.00     | 00.00 | 163.00 |
| M                                   | ORNAMENT-KIA NO.115             | / REC             |     |              | 1.00   | 32.00      | 00.00 | 32.00  |
| M                                   | COVER-RR BUMPER                 | / OR              |     |              | 1.00   | 651.00     | 00.00 | 651.00 |
| M                                   | COVER-RR BUMPER LWR             | / OR ? / CUT      |     |              | 1.00   | 241.00     | 00.00 | 241.00 |
| M                                   | COVER-RR BUMPER FOG LAMP, RH    | / CUT             |     |              | 1.00   | 19.00      | 00.00 | 19.00  |
| M                                   | COVER-RR BUMPER FOG LAMP, LH    | / CUT             |     |              | 1.00   | 19.00      | 00.00 | 19.00  |
| M                                   | LAMP ASSY-SIDE T/SIGNAL, RH     | X NAI / CUT       |     |              | 1.00   | 181.00     | 00.00 | 181.00 |
| M                                   | LAMP ASSY-SIDE T/SIGNAL, LH     | X NAI / CUT       |     |              | 1.00   | 181.00     | 00.00 | 181.00 |
| M                                   | EXTN WIRING ASSY-BWS            | X NAI / OR        |     |              | 1.00   | 207.00     | 00.00 | 207.00 |
| M                                   | BRACKET-RR BEAM UPR MTG, RH     | / ? / OR          |     |              | 1.00   | 9.00       | 00.00 | 9.00   |
| M                                   | BRACKET-RR BEAM UPR MTG, LH     | / ? / X NAI       |     |              | 1.00   | 9.00       | 00.00 | 9.00   |
| M                                   | BRACKET-RR BEAM LWR, CTR        | / ? / OR          |     |              | 1.00   | 6.00       | 00.00 | 6.00   |
| M                                   | BRACKET-RR BEAM LWR MTG         | / ? / OR          |     |              | 2.00   | 6.00       | 00.00 | 12.00  |
| M                                   | ANTENNA ASSY-SMARTKEY           | / X NAI           |     |              | 1.00   | 46.00      | 00.00 | 46.00  |
| M                                   | BEAM-RR BUMPER                  | / OR              |     |              | 1.00   | 318.00     | 00.00 | 318.00 |
| M                                   | STAY-RR BUMPER RH               | / ? / OT          |     |              | 1.00   | 65.00      | 00.00 | 65.00  |
| M                                   | STAY-RR BUMPER LH               | / ? / OT          |     |              | 1.00   | 65.00      | 00.00 | 65.00  |
| M                                   | COVER-RR BUMPER UNDER, RH       | / ? / X NAI       |     |              | 1.00   | 33.00      | 00.00 | 33.00  |
| M                                   | BRACKET ASSY-RR BPR SIDE UPR, L | / ? / X NAI       |     |              | 1.00   | 25.00      | 00.00 | 25.00  |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| YEO CHOK LIH<br><br>BLK 593B MONTREAL LINK<br>#15-56<br>SINGAPORE 752593<br><br>Contact No | Cust No/Name LCV11003/YEO CHOK LIH<br>Reg No/Reg Date SMP18255 / 02/09/201<br>Date In/Mileage / 0<br>Chassis No KNAF5416MK5052969<br>Engine No G4FGKH749566<br>Make/Model KIA/CERATO 1.6 A GT LINE H171<br>Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK |

| Account No                      | Terms                           | Date/Time Printed | CSE     | Operator     | WIP No | Qty  | Unit Price | Disc% | Amount  |
|---------------------------------|---------------------------------|-------------------|---------|--------------|--------|------|------------|-------|---------|
| LCV11003                        | CRDVCH                          | 25/03/2021/ 13:30 |         | 442 / CocoLu | 30926  |      |            |       |         |
| Description of Goods / Services |                                 |                   |         |              |        |      |            |       |         |
| M                               | BRACKET-ASSY RR BPR SIDE UPR R  | 00                | OR      |              |        | 1.00 | 31.00      | 00.00 | 31.00   |
| M                               | PANEL ASSY-TRUNK LID            | 00                | X NM    |              |        | 1.00 | 1297.00    | 00.00 | 1297.00 |
| M                               | HINGE ASSY-TRUNK LID, LH        | 00                | X NM    |              |        | 1.00 | 97.00      | 00.00 | 97.00   |
| M                               | HINGE ASSY-TRUNK LID, RH        | 00                | X NM    |              |        | 1.00 | 97.00      | 00.00 | 97.00   |
| M                               | PANEL ASSY-BACK                 | 00                | (photo) |              |        | 1.00 | 324.00     | 00.00 | 324.00  |
| M                               | LOGO ASSY-KIA SUB               | 00                |         |              |        | 1.00 | 32.00      | 00.00 | 32.00   |
| M                               | EMBLEM-CERATO                   | 00                |         |              |        | 1.00 | 28.00      | 00.00 | 28.00   |
| M                               | EMBLEM-GT LINE                  | 00                |         |              |        | 1.00 | 45.00      | 00.00 | 45.00   |
| M                               | TRIM ASSY-TRUNK LID             | 00                | X NM    |              |        | 1.00 | 202.00     | 00.00 | 202.00  |
| M                               | W/STRIP-TRUNK LID OPNG          | 00                | X NM    |              |        | 1.00 | 100.00     | 00.00 | 100.00  |
| M                               | LATCH ASSY-TRUNK LID            | 00                | X NM    |              |        | 1.00 | 112.00     | 00.00 | 112.00  |
| M                               | TRIM ASSY-RR TRANSVERSE         | 00                | X NM    |              |        | 1.00 | 41.00      | 00.00 | 41.00   |
| M                               | TRIM ASSY-LUGGAGE SIDE RH       | 00                | X NM    |              |        | 1.00 | 200.00     | 00.00 | 200.00  |
| M                               | MAT ASSY-LUGGAGE COVERING       | 00                | X NM    |              |        | 1.00 | 211.00     | 00.00 | 211.00  |
| M                               | PANEL ASSY-REAR FLOOR, RR       | 00                | X NM    |              |        | 1.00 | 219.00     | 00.00 | 219.00  |
| M                               | LAMP ASSY-REAR COMB INSIDE, RH  | 00                | X NM    |              |        | 1.00 | 608.00     | 00.00 | 608.00  |
| M                               | LAMP ASSY-REAR COMB INSIDE, LH  | 00                | X NM    |              |        | 1.00 | 608.00     | 00.00 | 608.00  |
| M                               | LAMP ASSY-REAR COMB OUTSIDE, RH | 00                | X NM    |              |        | 1.00 | 675.00     | 00.00 | 675.00  |
| M                               | LAMP ASSY-REAR COMB OUTSIDE, LH | 00                | X NM    |              |        | 1.00 | 675.00     | 00.00 | 675.00  |
| M                               | LAMP ASSY-CENTER GARNISH        | 00                | X NM    |              |        | 1.00 | 690.00     | 00.00 | 690.00  |
| M                               | MUFFLER ASSY-REAR               | 00                | X NM    |              |        | 1.00 | 757.00     | 00.00 | 757.00  |
| M                               | PROTECTOR-HEAT REAR             | 00                | X NM    |              |        | 1.00 | 136.00     | 00.00 | 136.00  |

STER (LKK) 00-NH AL  
 25/3/21 4.30pm Excess -?  
 P/P  
 M Bel SJ  
 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by \_\_\_\_\_  
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Authorized signatory and company stamp

7% GST on **21338.00** **Nett** **21,338.00**  
**1493.66**  
**Total Payable 22,831.66**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.