



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YEO CHOK LIH	Cust No/Name	LCV11003/YEO CHOK LIH
BLK 593B MONTREAL LINK	Reg No/Reg Date	SMP1825S / 02/09/201
#15-56	Date In/Mileage	/ 0
SINGAPORE 752593	Chassis No	KNAF5416MK5052969
Contact No	Engine No	G4FGKH749566
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11003	CRDVCH	25/03/2021/ 13:30		442 / CocoLu	30926			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								400.00
RENEW FRT BUMPER		400 X 1						
M SUNDRY								350 20.00
SPRAY PAINT FOR FRT BUMPER		350 X 1						
E PNT88000								60.00
REMOVE & INSTALL FRT PARKING SENSOR								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								4000.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT								
REPAIR REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH		3 X 400						1200
E PNT88000								300.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
E PNT88000								300.00
REMOVE & INSTALL CARPAT AND REAR SEATS								
E PNT98000								3500.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT								
REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH		4 X 350						1400
E PNT88000								100.00
REMOVE & INSTALL REAR SPOILER								80
M SUNDRY								40 120.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								50.00
REAR NUMBER PLATE WITH FRAME								
M SUNDRY								40.00
C&C LOGO								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YEO CHOK LIH	Cust No/Name	LCV11003/YEO CHOK LIH
BLK 593B MONTREAL LINK	Reg No/Reg Date	SMP1825S / 02/09/201
#15-56	Date In/Mileage	/ 0
SINGAPORE 752593	Chassis No	KNAF5416MK5052969
Contact No	Engine No	G4FGKH749566
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11003	CRDVCH	25/03/2021/ 13:30		442 / CocoLu	30926			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								500.00
TO STRAIGHTEN REAR BOTH CHASSIS								
A 90000001								300.00
RENEW REAR EXHAUST SYSTEM								
M SUNDRY								20.00
Sundry								
M COVER-FR BUMPER / CRU ?					1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER					1.00	485.00	00.00	485.00
M COVER-FR BUMPER FOG LAMP,LH / CUT					1.00	15.00	00.00	15.00
M LAMP ASSY-FRONT FOG,LH X					1.00	303.00	00.00	303.00
M MOULDING-FRONT BUMPER,LH X					1.00	216.00	00.00	216.00
M LAMP ASSY-SIDE REPEATER,LH / CUT					1.00	143.00	00.00	143.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	84.00
M BRACKET-FR BUMPER UPR SIDE MTG ?					1.00	22.00	00.00	22.00
M ULTRASONIC SENSOR ASSY-P.A.S / BR					1.00	163.00	00.00	163.00
M ORNAMENT-KIA NO.115 / REC					1.00	32.00	00.00	32.00
M COVER-RR BUMPER / BR					1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR / BR					1.00	241.00	00.00	241.00
M COVER-RR BUMPER FOG LAMP,RH ?					1.00	19.00	00.00	19.00
M COVER-RR BUMPER FOG LAMP,LH / CUT					1.00	19.00	00.00	19.00
M LAMP ASSY-SIDE T/SIGNAL,RH X					1.00	181.00	00.00	181.00
M LAMP ASSY-SIDE T/SIGNAL,LH X					1.00	181.00	00.00	181.00
M EXTN WIRING ASSY-BWS ?					1.00	207.00	00.00	207.00
M BRACKET-RR BEAM UPR MTG,RH ?					1.00	9.00	00.00	9.00
M BRACKET-RR BEAM UPR MTG,LH ?					1.00	9.00	00.00	9.00
M BRACKET-RR BEAM LWR,CTR ?					1.00	6.00	00.00	6.00
M BRACKET-RR BEAM LWR MTG ?					2.00	6.00	00.00	12.00
M ANTENNA ASSY-SMARTKEY ?					1.00	46.00	00.00	46.00
M BEAM-RR BUMPER / BR ?					1.00	318.00	00.00	318.00
M STAY-RR BUMPER RH ?					1.00	65.00	00.00	65.00
M STAY-RR BUMPER LH ?					1.00	65.00	00.00	65.00
M COVER-RR BUMPER UNDER,RH ?					1.00	33.00	00.00	33.00
M BRACKET ASSY-RR BPR SIDE UPR,L ?					1.00	25.00	00.00	25.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YEO CHOK LIH	Cust No/Name LCV11003/YEO CHOK LIH
BLK 593B MONTREAL LINK	Reg No/Reg Date SMP1825S / 02/09/201
#15-56	Date In/Mileage / 0
SINGAPORE 752593	Chassis No KNAF5416MK5052969
Contact No	Engine No G4FGKH749566
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV11003	CRDVCH	25/03/2021/ 13:30		442 / CocoLu	30926
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET-ASSY RR BPR SIDE UPR R	?	1.00	31.00	00.00	31.00
M PANEL ASSY-TRUNK LID	00	1.00	1297.00	00.00	1297.00
M HINGE ASSY-TRUNK LID,LH	?	1.00	97.00	00.00	97.00
M HINGE ASSY-TRUNK LID,RH	?	1.00	97.00	00.00	97.00
M PANEL ASSY-BACK	00 (photo)	1.00	324.00	00.00	324.00
M LOGO ASSY-KIA SUB	rec	1.00	32.00	00.00	32.00
M EMBLEM-CERATO	rec	1.00	28.00	00.00	28.00
M EMBLEM-GT LINE	rec	1.00	45.00	00.00	45.00
M TRIM ASSY-TRUNK LID	?	1.00	202.00	00.00	202.00
M W/STRIP-TRUNK LID OPNG	?	1.00	100.00	00.00	100.00
M LATCH ASSY-TRUNK LID	?	1.00	112.00	00.00	112.00
M TRIM ASSY-RR TRANSVERSE	?	1.00	41.00	00.00	41.00
M TRIM ASSY-LUGGAGE SIDE RH	X	1.00	200.00	00.00	200.00
M MAT ASSY-LUGGAGE COVERING	X	1.00	211.00	00.00	211.00
M PANEL ASSY-REAR FLOOR,RR	?	1.00	219.00	00.00	219.00
M LAMP ASSY-REAR COMB INSIDE,RH	?	1.00	608.00	00.00	608.00
M LAMP ASSY-REAR COMB INSIDE,LH	?	1.00	608.00	00.00	608.00
M LAMP ASSY-REAR COMB OUTSIDE,RH	?	1.00	675.00	00.00	675.00
M LAMP ASSY-REAR COMB OUTSIDE,LH	?	1.00	675.00	00.00	675.00
M LAMP ASSY-CENTER GARNISH	?	1.00	690.00	00.00	690.00
M MUFFLER ASSY-REAR	?	1.00	757.00	00.00	757.00
M PROTECTOR-HEAT REAR	BT	1.00	136.00	00.00	136.00

Steer (LKR) 00-NH AL
Excess -?
P/P
M Bel sy
9 dgs

Confirm & accepted by

Nett 21,338.00
7% GST on 21338.00 1493.66
Total Payable 22,831.66

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.