

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5402E**AAD2103-110***Not Authored**8220/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

23 MAR 2021**SHC5402E**

VF1ABL15AUC279583

RENAULT

LATITUDE

20/03/2021

TOKIO

04/11/2014

PART

	LIST	
1 BUMPER COVER REAR	\$ 11	561.70
1 BUMPER LOWER REAR	\$ 12	411.90
1 BUMPER BRACKET CTR REAR	\$ 12	98.10
1 BUMPER BRACKET SIDE RH REAR	\$ 12	82.10
1 BUMPER RETAINER RH REAR	\$ 12	59.80
1 BUMPER BRACKET SIDE LH REAR	\$ 12	80.80
1 BUMPER RETAINER LH REAR	\$ 12	54.20
1 BUMPER BEAM REAR	\$ 11	547.80
1 BUMPER BEAM BRACKET LH REAR	\$ 12	114.50
1 BUMPER BEAM BRACKET RH REAR	\$ 11	114.50
	\$	2,125.40
	10% \$	212.54
	\$	1,912.86

Specical Nett

1SET PARKING AID	\$ 12	700.00
1SET REAR BUMPER CLIP	\$ 12	66.00
1SET BUMPER BRACKET CTR CLIP	\$ 12	33.00
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ 12	10.00
1SET BUMPER RETAINER RH CLIP RR	\$ 12	20.00
1SET BUMPER BRACKET SIDE CLIP LH RR	\$ 12	10.00
1SET BUMPER RETAINER CLIP LH RR	\$ 12	20.00
1SET BUMPER LOWER REAR CLIP	\$ 12	66.00
	\$	925.00
TOTAL PARTS	\$	2,837.86

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *2201*

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of Parts, \$ *na* 3,000.00 X
 Adjust And Realign The Same

To Rust-Proofing Of The Affected Areas. \$ *na* 170.00 X

To reinstall rear bumper parking sensor. \$ *na* 170.00 X

To transfer of bootlid fittings, attachments and
 perform water seepage test. \$ *na* 170.00 X

To repair and realign rear exhaust pipe. \$ *na* 170.00 X

To drop rear exhaust box, renew the same, to repair
 and realign centre exhaust pipe. \$ *na* 170.00 X

To transfer of rear end panel fittings, attachment and
 perform water seepage test. \$ *na* 170.00 X

To transfer of rear windscreen fittings and conduct
 water seepage test. \$ *na* 170.00 X

To check steering geometry and computer wheel
 alignment \$ *na* 220.00 X

To Check Electrical Lighting Concerned. \$ *na* 170.00 X

TOTAL \$ 7,580.00

Over All Total \$ 12,330.72

**(LUMP SUM)
 Repair Days**

*20 DAYS
 1 day*

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: