

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD636A**AAD2103-108***Not Authored
11 Days @ 9750/h*

Vehicle No.:

Chassis No.:

23 MAR 2021

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD636A

VF1ABL15AUC283390

RENAULT

LATITUDE

19/03/2021

EQ

30/11/2017

PART**LIST**

- 1 DOOR PANEL FRT RH
- 1 DOOR WEATHERSTRIP FRT RH
- 1 DOOR HINGE UPPER FRT RH
- 1 DOOR HINGE LOWER FRT RH
- 1 DOOR REGULATOR FRT RH
- 1 DOOR REGULATOR MOTOR FRT RH
- 1 DOOR HANDLE OUTER FRT RH
- 1 DOOR HANDLE MODULE FRT RH
- 1 DOOR PANEL REAR RH *1458.00*
- 1 DOOR HINGE UPPER REAR RH
- 1 DOOR HINGE LOWER REAR RH
- 1 DOOR REGULATOR REAR RH
- 1 DOOR REGULATOR MOTOR REAR RH
- 1 DOOR HANDLE OUTER REAR RH
- 1 DOOR HANDLE MODULE REAR RH
- 1 DOOR GLASS REAR RH
- 1 DOOR 1/4 GLASS REAR RH
- 1 DOOR MOULDING REAR RH
- 1 DOOR FINISHER REAR RH
- 1 DOOR WEATHERSTRIP REAR RH
- 1 DOOR SEAL REAR RH
- 1 DOOR FINISHER INNER REAR RH
- 1 DOOR GLASS RUNNER SEAL REAR RH
- 1 DOOR WAIST SEAL OUTER REAR RH
- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 FENDER PANEL REAR RH
- 1 WHEELARCH REAR RH
- 1 TAILLAMP RH
- 1 ROCKER PANEL OUTER RH

- \$ *R* 2,844.66 ✓
- \$ *S* 410.27 X
- \$ *R* 261.28 X
- \$ *R* 300.55 X
- \$ *S* 505.19 X
- \$ *S* 796.46 X
- \$ *S* 477.76 X
- \$ *S* 133.60 X
- \$ *R* 2,844.66 ✓
- \$ *R* 241.60 X
- \$ *D* 169.90 ✓
- \$ *D* 450.60 ✓
- \$ *T* 758.10 ✓
- \$ *S* 42.10 X
- \$ *S* 133.40 X
- \$ *Shatter* 364.70 ✓
- \$ *"* 229.20 ✓
- \$ *M* 100.50 ✓
- \$ *S* 230.30 X
- \$ *LT* 311.60 *508.00 155.80*
- \$ *S* 119.80 X
- \$ *S* 183.70 X
- \$ *LT* 116.10 ✓
- \$ *S* 99.40 X
- \$ *R* 561.70 X
- \$ *S* 411.90 X
- \$ *R* 1,933.20 ✓
- \$ *S* 275.40 X
- \$ *CM* 401.40 ✓
- \$ *R* 1,184.99 ✓

Trans-cab Auto Services Pte Ltd

AAD2103-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD636A

TOTAL	\$	16,894.02
10%	\$	1,689.40
	\$	15,204.62

Special Nett

1 REAR BUMPER CLIP	\$	nn	65.00	X
1SET FENDER SCREW	\$	nn	60.00	X
1 TYRE	\$	sn	300.00	X
1 RIM	\$	sn	350.00	X
1 DOOR FINISHER CLIP	\$	nn acc	60.00	X
1 DOOR MOULDING CLIP	\$	nn	60.00	X
1 DOOR STICKER TRANSCAB	\$	nn	100.00	60sn
1 DOOR STICKER TEL NO.	\$	nn	100.00	60sn
1 DOOR STICKER CLASSIC	\$	nn	100.00	15sn
2 WINDSCREEN SEALANT	\$	nn	150.00	40sn
1 WINDSCREEN MOULDING	\$	nn	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	30sn
TOTAL	\$		1,675.00	
TOTAL PARTS	\$		16,879.62	

LABOUR

Towing fees	\$	170.00	50/
To transfer of door fittings, attachment and perform water seepage test.	\$	300.00	120/
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	120/
To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.	\$	380.00	100/

Trans-cab Auto Services Pte Ltd**AAD2103-108**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD636A

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 1,400.00 1200

To rust-proofing and apply undercoat of the affected
areas.

\$ 240.00 120

Putty and spray painting of the affected portion.

\$ 1,400.00 1100

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 20

TOTAL \$ 4,750.00**Over All Total \$ 21,629.62****LUMP SUM (REPAIR DAY)****20 DAYS**

8 day,

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: