



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5500K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER REFLECTOR ASSY, REFLEX, RH (DISC 25%)	SCRATCHED	39.00	29.25
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CRUMPLED	374.50	280.88
2	PIXEL STICKER @\$60.00 (SN)	CRUMPLED	120.00	120.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	332.70	-
1	PAD, RR BUMPER, RH & LH, 3	SERVICEABLE	11.00	-
1	PAD, RR BUMPER, RH & LH, 2	SERVICEABLE	4.00	-
1	PAD, RR BUMPER, RH & LH, 1	SERVICEABLE	4.00	-
1	PAD, RR BUMPER, CTR	SERVICEABLE	11.00	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	SERVICEABLE	651.00	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	LENS & BODY, REAR COMBINATION LAMP, NO.2	SERVICEABLE	261.00	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	SERVICEABLE	339.60	-
1	COVER, REAR FLOOR UNDER CENTER	SERVICEABLE	229.90	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	175.10	-
1	COVER, GUARD RR BUMPER LOWER	SERVICEABLE	22.00	-
1	CLIPS PIECE, FRT & RR BUMPER	SERVICEABLE	4.50	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	132.60	-
1	SEAL, RR BUMPER ARM, RH & LH	SERVICEABLE	11.30	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	485.60	-
			3,425.80	430.13
<b><u>LABOUR</u></b>				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY.			507.00	200.00
SPRAY PAINT.			738.00	200.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM.		NOT NECESSARY	120.00	-
TO REPLACE SUNDRY PARTS.		NOT NECESSARY	100.00	-
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00

Report Ref No. CC3/EQI21003929/Qvf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,605.00	420.00
GRAND TOTAL			5,030.80	850.13
RECOMMENDED COST OF REPAIRS				850.13

Report Ref No. CC3/EQI21003929/Qvf3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.