

Section A - Accident Details

Registration Number	SHB5500K
Case Reference Number	TAX/03/21/2076
Registration Date	12/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN GUO YONG (CHEN GUOYONG)
Type of Accident	Head to Rear
Accident Date and Time	24/3/2021 9:30 AM
Accident Reported Date and Time	24/3/2021 3:48 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110208
Special Instruction to ARC, if any	TP/ REAR RIGHT PORTION
Prepared Date and Time	25/3/2021 9:27 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$2,813.29	\$430.13
Total Other Cost	\$360.00	\$20.00
TOTAL COST	\$4,418.29 5030.80	\$850.13 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / EQ
ARC / Surveyor Sign Off Date	25/03/2021 9:43 AM	25/03/2021 3:29 PM
Signature		
Remarks		P/P, Before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0055	Invoice Number	
Quotation Date	08.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00 ✓
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$20.00 ✓

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	100.00	\$0.00	Replace	Repair R
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check ✓
		52462-47130	PAD, RR BUMPER, RH & LH, 3	0.00	\$11.00	0.00	\$0.00	Replace	Not Given X
		52462-47030	PAD, RR BUMPER, RH & LH, 2	0.00	\$4.00	0.00	\$0.00	Replace	Not Given X
		52462-47020	PAD, RR BUMPER, RH & LH, 1	0.00	\$4.00	0.00	\$0.00	Replace	Not Given X
		52461-47070	PAD, RR BUMPER, CTR	0.00	\$11.00	0.00	\$0.00	Replace	Not Given X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Not Given X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace CRU
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Not Given X
		81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$339.60	0.00	\$0.00	Replace	Not Given X
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Not Given X
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$175.10	0.00	\$0.00	Replace	Not Given X
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1.00	\$39.00	25.00	\$29.25	Replace	Replace SC R
		52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$22.00	0.00	\$0.00	Replace	Not Given X SVC
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace CRU

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2021

User ID : PohSuan

		52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.50	0.00	\$0.00	Replace	Not Given X
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given X
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.30	0.00	\$0.00	Replace	Not Given X
Total					\$3,365.80		\$430.13		

SVC
SVC
SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

430.13 /
+ 200.00 /
+ 220.00 /
850.13 /

P/P
\$850.13
2 days
SHB 5500K