

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SKW 9644 G**
 Model : Toyota Wish
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

2011

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front fender LH	1	\$ 987.00	\$ 689.20 987.00
2	Front fender inner cowling LH	1	\$ 180.30	\$ 146.40 180.30
3	Front door LH	1	\$ 1,526.50	\$ 1,121.75 1,526.50
4	Front door black tape LH	1	\$ 92.60	\$ 25.00 92.60
5	Front door weatherstrip LH	1	\$ 272.00	\$ 103.59 272.00
6	Front door inner lock LH	1	\$ 358.30	\$ 197.90 358.30
7	Front door inner lock striker LH	1	\$ 68.00	\$ 68.00
8	Front door frame rubber LH	1	\$ 106.90	\$ 106.90
9	Front door trimboard LH	1	\$ 397.90	\$ 397.90
10	Front door regulator LH	1	\$ 332.00	\$ 158.16 332.00
11	Front door regulator motor LH	1	\$ nn 421.00	\$ 230.00 421.00
12	Front door glass channel LH	1	\$ 177.30	\$ 154.30 177.30
13	Front door outer handle LH	1	\$ 210.00	\$ 210.00
14	Front door outer moulding LH	1	\$ 104.00	\$ 104.00
15	Front door hinge LH	2	\$ 48.60 85.00	\$ 97.20 170.00
16	Front door checker LH	1	\$ 131.90	\$ 131.90
17	Side mirror assy LH	1	\$ 685.00	\$ 685.00
18	Door centre pillar LH	1	\$ 827.50	\$ 310.40 827.50
19	Rear door LH	1	\$ 1,467.50	\$ 1,115.00 1,467.50
20	Rear door black tape LH	1	\$ 92.60	\$ 25.00 92.60
21	Rear door weatherstrip LH	1	\$ 272.00	\$ 103.20 272.00
22	Rear door inner lock LH	1	\$ 328.90	\$ 328.90
23	Rear door inner lock striker LH	1	\$ 86.50	\$ 86.50
24	Rear door trimboard LH	1	\$ 397.90	\$ 397.90
25	Rear door frame rubber LH	1	\$ 106.90	\$ 106.90
26	Rear door regulator LH	1	\$ 332.00	\$ 158.16 332.00
27	Rear door regulator motor LH	1	\$ nn 421.00	\$ 230.00 421.00
28	Rear door glass channel LH	1	\$ 177.30	\$ 177.30
29	Rear door outer handle LH	1	\$ 210.00	\$ 210.00
30	Rear door outer moulding LH	1	\$ 104.00	\$ 104.00
31	Rear door hinge LH	2	\$ 48.60 85.00	\$ 97.20 170.00
32	Rear door checker LH	1	\$ 102.80	\$ 102.80
33	Side skirt LH	1	\$ 785.30	\$ 300.00 785.30
34	Rocker panel LH	1	\$ nn 615.00	\$ 432.00 615.00
35	Rear fender LH	1	\$ 1,137.50	\$ 1,137.50
36	Rear fender inner trim board LH	1	\$ 918.00	\$ 918.00
37	Rear fender inner cowling LH	1	\$ 185.90	\$ 185.90
38	Rear fender side glass moulding LH	1	\$ 227.60	\$ 227.60

DDV ✓
 TNV ✓
 DDV ✓
 NECV ✓
 TNV ✓
 JMV ✓
 NDX
 NDX
 BRV
 BTV ✓
 BTV ✓
 JMV ✓
 NDX
 NDX
 PDV ✓
 DDV ✓
 NECV ✓
 TNV ✓
 JMV ✓
 NDX
 BRV ✓
 NDX
 NDX
 NDX
 BTV ✓
 NDX
 NDX
 NDX
 BRV ✓
 DDV ✓
 CUTXR
 NDX
 NDX
 NDX

39	Front knuckle arm LH	1	\$	398.00	\$	398.00	NDX
40	Front knuckle arm bearing LH	1	\$ nn	245.50	\$	148.00 245.50	IN V
41	Front shock absorber LH	1	\$ nn	364.00	\$	X 364.00	BT V
42	Front lower arm LH	1	\$ nn	535.25	\$	345.70 535.25	BT V
43	Steering rack	1	\$ nn	1,108.00	\$	X 1,108.00	BT V
44	Rear shock absorber LH	1	\$ nn	412.50	\$	116.00 412.50	BT V
45	Rear axle	1	\$	1,688.00	\$	1,688.00	NDX
46	Rear wheel hub with bearing LH	1	\$ nn	369.80	\$	345.50 369.80	IN V
Parts Sub Total:					\$	8,138.36	20,307.95
Discount 25%:					\$	2,034.59	5,076.99
PARTS TOTAL:					\$		15,230.96

6103.77

Nos.	SPECIAL NETT ITEMS	Qty	Unit	S\$	TOTAL S\$		
1	Sundries	1	\$	80.00	\$	80.00 NNX	
2	Front fender sealant	1	\$	100.00	\$	40.00 100.00 NECV	
3	Front fender inner cowling clips	1	\$	50.00	\$	20.00 50.00 NECV	
4	Front door sealant	1	\$ nn	100.00	\$	40.00 100.00 NECV	
5	Front door speaker	1	\$	210.00	\$	210.00 NNX	
6	Front door trimboard clips	1	\$	50.00	\$	30.00 50.00 NECV	
7	Side mirror seal	1	\$	60.00	\$	60.00 NNX	
8	Door centre pillar sealant	1	\$	100.00	\$	100.00 NNX	
9	Rear door sealant	1	\$ nn	100.00	\$	40.00 100.00 NECV	
10	Rear door speaker	1	\$	210.00	\$	210.00 NNX	
11	Rear door trimboard clips	1	\$	50.00	\$	30.00 50.00 NECV	
12	Side skirt clips	1	\$	50.00	\$	30.00 50.00 NECV	
13	Rocker panel sealant	1	\$ nn	100.00	\$	30.00 100.00 NECV	
14	Chassis sticker	1	\$	180.00	\$	120.00 180.00 NECV	
15	Rear fender sealant	1	\$	100.00	\$	100.00 NNX	
16	Rear fender inner trim board clips	1	\$	50.00	\$	50.00 NNX	
17	Rear fender inner cowling clips	1	\$	50.00	\$	50.00 NNX	
18	Rear fender side glass sealant	1	\$	100.00	\$	100.00 NNX	
19	Rear fender side glass inner seal	1	\$	60.00	\$	60.00 NNX	
20	Rear fender side glass primer & cleaner	1	\$	80.00	\$	80.00 NNX	
21	Front & rear alloy rim LH	2	\$	200.00 980.00	\$	400.00 1,960.00 CUT X R	
22	Front & rear tyre LH	2	\$	480.00	\$	480.00 NDX	
SPECIAL NETT TOTAL:					\$		780.00

Nos.	LABOUR		SS
1	R&R front door component		\$ 90.00 150.00
2	R&R Door centre pillar inner garnish		\$ 50.00 100.00
3	R&R rear door component		\$ 80.00 150.00
4	R&R rear fender side glass		\$ 250.00
5	R&R fuel tank pipe		\$ 150.00
6	R&R rear bumper reverse sensor		\$ 60.00 100.00
7	R&R front & rear under carriage		\$ 300.00 600.00
8	R&R front & rear tyre and balancing		\$ 30.00 200.00
9	R&R steering rack		\$ 100.00 150.00
10	Wheel alignment		\$ 60.00 180.00
11	Check wiring		\$ 60.00 100.00
12	Upholstery		\$ 300.00
13	Diagnostic reset fault code		\$ 300.00
14	Panel beat	1200	\$ 1,400.00 1,800.00
15	Rust proofing		\$ 100.00 200.00
16	Spray paint	1000	\$ 1,200.00 1,800.00
		LABOUR TOTAL :	\$ 6,530.00

Survey 26/3/2021
Resurvey 29/3/2021
TCU in
Mw

3520.00
PARTS TOTAL : \$ 15,230.96
SPECIAL NETT TOTAL : \$ 4,800.00
LABOUR TOTAL : \$ 6,530.00
GRAND TOTAL : \$ 26,560.96

Lump sum repair
Repair days 8

L/S 8300/-
TCU in
Mw

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: