



陳林峰時私人有限公司
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : YP5967Y
Date of Accident : 24 March 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Pun Ving Kee

Date : 25 March 2021

Estimate To Repair SMD7587C - Hyundai ELANTRA AD 1.6 GLS AT (AMS)

Chassis No : KMHD841CMJU744911

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 460.00
02	8 ps	rear bumper clips @ \$5.50	\$ 44.00
03	2 ps	rear bumper reflector @ \$39.00	\$ 78.00
04	2 ps	rear bumper retainer @ \$49.00	\$ 98.00
05	1 pc	rear bumper reinforcement	\$ 339.00
06	3 ps	rear bumper bottom bracket @ \$25.00	\$ 75.00
07	1 pc	rear bumper lower centre garnish	\$ 257.00
08	1 pc	bootlid	\$ 1,582.00
09	1 pc	bootlid rubber	\$ 286.00
10	1 pc	rear bumper lower splash cover	\$ 82.00
11	8 ps	rear bumper lower splash cover clips @ \$4.50	\$ 36.00
12	1 pc	rear end panel	\$ 379.00
13	1 pc	rear end panel inner trim	\$ 59.00
14	6 ps	rear end panel inner trim clips @ \$4.50	\$ 27.00
15	1 pc	bootlid Elantra badge	\$ 85.00
16	1 pc	bootlid Elite badge	\$ 75.00
17	1 pc	bootlid centre emblem badge	\$ 85.00
			\$ 4,047.00
		Less 20 %	\$ 809.40
			\$ 3,237.60
		<u>SPECIAL NETT ITEMS</u>	
18	1 set	rear bumper parking sensor	\$ 350.00
			\$ 350.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00
02		To rust-proofing of the affected areas.	\$ 150.00
03		To check electrical lighting concerned.	\$ 80.00
04		To reinstall of rear bumper parking sensor.	\$ 80.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 850.00
06		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 2,110.00
		Total	\$ 5,697.60