

Section A - Accident Details

Registration Number	SHC4601D
Case Reference Number	TAX/03/21/2071
Registration Date	8/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOHAMAD NIZAMULMULUK BIN HUSSAIN
Type of Accident	Head to Rear
Accident Date and Time	23/3/2021 8:35 AM
Accident Reported Date and Time	23/3/2021 2:33 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110175
Special Instruction to ARC, if any	TOWED \$ /FRONT AND REAR PORTION
Prepared Date and Time	24/3/2021 2:19 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,590.00	\$1,650.00
Total Spray Cost	\$5,720.00	\$1,400.00
Total Spare Part Cost	\$41,453.43	\$11,326.60
Total Other Cost	\$1,846.00	\$480.00
TOTAL COST	\$51,609.43	\$14,856.60
Lump Sum Total	\$51,600.00	\$14,850.00 (L/S)
Number of Repair Days	14.0	11.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	31/03/2021 8:15 PM	31/03/2021 3:18 PM
Signature		
Remarks	Total number of repair days = 11 days. SUP = + 4 days.	L/S, After paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0266	Invoice Number	
Quotation Date	20.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$450.00	\$200.00 /supp
TO REPAIR FRONT FENDER RH	\$200.00	\$100.00 /supp
TO REPAIR SPARE TYRE FLOOR PANEL	\$250.00	\$150.00 /supp
TO REPAIR REAR PORTION	\$845.00	\$600.00 /
TO REPAIR FRONT PORTION	\$845.00	\$600.00 /
Total Labour	\$2,590.00	\$1,650.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$250.00	\$200.00 /supp
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 /supp
TO RESPRAY REAR SPARE TYRE PANEL	\$250.00	\$200.00 /supp
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO REPSRAY REAR DOOR LH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00 /
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$5,720.00	\$1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$60.00 /
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00 /

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/04/2021

User ID : PohSuan

TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$100.00	/
TO REMOVE AND REFIX TAILGATE GLASS	\$120.00	\$60.00	/
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$40.00	/
TO REMOVE & REFIT EXHAUST	\$120.00	\$30.00	/
TO REMOVE AND REFIT ENGINE WIRE ROOM	\$200.00	\$0.00	
TO REMOVE AND REFIX ENGINE WIRE HARDNESS	\$120.00	\$0.00	
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00	
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00	
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00	/
TO WASH AND VACUUM	\$60.00	\$0.00	
TOWING CHARGE	\$126.00	\$90.00	/
Total Other Costs	\$1,846.00	\$480.00	/

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	DD
		75574-47020	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	Nec
		75574-47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	Nec
		68105-47122	TAILGATE DOOR GLASS	0.00	\$1,090.90	0.00	\$0.00	Replace	Not Given	X SVC
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	Nec
		75575-47020	MOULDING, BACK WINDOW, LOWER NO.2	1.00	\$29.40	25.00	\$22.05	Replace	Replace	Nec
		64821-47030	TAILGATE LOWER WINDOW GLASS	0.00	\$721.30	0.00	\$0.00	Replace	Not Given	X SVC
		56117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	1.00	\$27.30	25.00	\$20.48	Replace	Replace	Nec
		68294-47050	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1.00	\$17.40	25.00	\$13.05	Replace	Replace	Nec
		82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Not Given	X SVC
		68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	X SVC
		69350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace	Jum
		69415-47020	TAILGATE LOCK, COVER	1.00	\$15.70	25.00	\$11.78	Replace	Replace	BR
		67938-47031C0	TAILGATE TRIM, LH	0.00	\$85.90	0.00	\$0.00	Replace	Check	X
		67937-47031C0	TAILGATE TRIM, RH	0.00	\$88.30	0.00	\$0.00	Replace	Check	X
		67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check	X SVC
		64790-47030C0	TAILGATE TRIM, UPPER	0.00	\$49.60	0.00	\$0.00	Replace	Check	X
		67750-47071C0	TAILGATE, BAORD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Not Given	X
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Check	X
		75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	Nec
		75442-47030	NAME PLATE (PRUIS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X SVC
		75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X SVC
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	pb
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	CRA
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X SVC
			STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X SVC
		76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	X SVC
		81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	X SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 20/04/2021

User ID : PohSuan

75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Check	X	SVC
53301-47060	HOOD PANEL	1.00	\$748.10	25.00	\$561.08	Replace	Replace	/	BD
53420-47070	HOOD HINRE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X	SVC
53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X	SVC
53510-47102	HOOD LOCK	1.00	\$128.90	25.00	\$96.68	Replace	Replace	/	Jam
86510-28130	HORN ASSY, HIGH	0.00	\$110.40	0.00	\$0.00	Replace	Check	X	SVC
86520-28180	HORN ASSY, LOW	0.00	\$110.40	0.00	\$0.00	Replace	Check	X	
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X	
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	/	CRA
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	/	CRA
65319-47120	WIPER WASHER INLET	0.00	\$36.90	0.00	\$0.00	Replace	Check	X	SVC
85315-47140	WIPER WASHER JAR	0.00	\$180.10	0.00	\$0.00	Replace	Check	X	
85330-47010	MOTOR NO:1, WIPER WASHER JAR	0.00	\$239.00	0.00	\$0.00	Replace	Check	X	
85330-60180	MOTOR NO:2, WIPER WASHER JAR	0.00	\$240.00	0.00	\$0.00	Replace	Check	X	SVC
88710-47150	TUBE & ACCESSORY	0.00	\$631.90	0.00	\$0.00	Replace	Check	X	
88703-47040	HOSE SUB-ASSY DISCHARGE	0.00	\$386.90	0.00	\$0.00	Replace	Check	X	
88460-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check	X	SVC
88704-47090	HOSE SUB-ASSY SUCTION	0.00	\$405.40	0.00	\$0.00	Replace	Check	X	
G9010-47031	RADIATOR ASSY UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Check	X	
G9225-47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Check	X	SVC
G9229-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	X	
G9110-47011	INVERTER BRACKET TRAY	0.00	\$251.60	0.00	\$0.00	Replace	Check	X	
16716-37010	INVERTER RADIATOR CUSHION	0.00	\$5.40	0.00	\$0.00	Replace	Check	X	SVC
G9200-49025	INVERTER W CONVERTER	0.00	\$5,390.20	0.00	\$0.00	Replace	Check	X	
16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Check	X	
16523-21050	CUSHION, RADIATOR	0.00	\$11.30	0.00	\$0.00	Replace	Check	X	SVC
16534-37010	SUPPORT RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	X	
16533-28051	SUPPORT RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X	
16535-20030	SUPPORT, RADIATOR	0.00	\$18.50	0.00	\$0.00	Replace	Check	X	SVC
57104-47020	RADIATOR LOWER SUPPORT	0.00	\$876.30	0.00	\$0.00	Replace	Check	X	
16572-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check	X	
16571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check	X	SVC
16261-37070	RADIATOR HOSE BYPASS NO.1	0.00	\$37.20	0.00	\$0.00	Replace	Check	X	
16264-37080	RADIATOR HOSE BYPASS NO.2	0.00	\$29.00	0.00	\$0.00	Replace	Check	X	
16267-37030	RADIATOR HOSE BYPASS NO.3	0.00	\$37.20	0.00	\$0.00	Replace	Check	X	SVC
16281-37030	RADIATOR HOSE BYPASS NO.4	0.00	\$37.20	0.00	\$0.00	Replace	Check	X	
	COOLANT	1.00	\$12.32	0.00	\$12.32	Replace	Replace	/	Nec
16480-28080	COOLANT RESERVE TANK	0.00	\$395.30	0.00	\$0.00	Replace	Check	X	SVC
16711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	X	
16712-37030	FAN SHROUD TOP	0.00	\$99.60	0.00	\$0.00	Replace	Check	X	
16361-37010	FAN BLADE	0.00	\$158.60	0.00	\$0.00	Replace	Check	X	SVC
16361-28360	FAN BLADE NO.2	0.00	\$204.20	0.00	\$0.00	Replace	Check	X	
16363-37010	FAN MOTOR NO.1	0.00	\$538.30	0.00	\$0.00	Replace	Check	X	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/04/2021

User ID : PohSuan

	16363-37020	FAN MOTOR NO.2	0.00	\$538.30	0.00	\$0.00	Replace	Check	X	SVC								
	17750-37010	INLET ASSY, AIR	0.00	\$232.50	0.00	\$0.00	Replace	Check	X		SVC							
	17700-38252	AIR CLEANER ASSY	0.00	\$929.90	0.00	\$0.00	Replace	Check	X			SVC						
	82111-47772	WIRE, ENGINE ROOM	0.00	\$5,567.10	0.00	\$0.00	Replace	Check	X				SVC					
	53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X					SVC				
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X						SVC			
	53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X							SVC		
	53851-47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X								SVC	
	53802-47050	FENDER FRT/LH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X									SVC
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X									
	53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X	SVC								
	53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X		SVC							
	67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	X			SVC						
	52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	X				SVC					
	90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace	X					SVC				
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X						SVC			
	52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X							SVC		
	52016-47030	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X								SVC	
	52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X									SVC
	89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check	X									
		SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	X	SVC								
	52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	X		SVC							
	52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	X			SVC						
	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X				SVC					
	52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X					SVC				
	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check	X						SVC			
	76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace	X							SVC		
	76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	X								SVC	
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	X									SVC
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Check	X									
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X	SVC								
	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	X		SVC							
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	X			SVC						
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X				SVC					
	64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	X					SVC				
	58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	X						SVC			
	58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Not Given	X							SVC		
	58311-47071	SPARE TYRE PANEL	1.00	\$667.70	100.00	\$0.00	Replace	Repair	X								SVC	
	82123-47040	WIRE, ENGINE, NO.3	0.00	\$74.00	0.00	\$0.00	Replace	Not Given	X									SVC
	82162-47B20	WIRE, FLOOR, NO.2	0.00	\$1,305.40	0.00	\$0.00	Replace	Not Given	X									
		BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Not Given	X	SVC								
	58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X		SVC							
	17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	0.00	\$0.00	Replace	Not Given	X			SVC						

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/04/2021

User ID : PohSuan

	17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	0.00	\$0.00	Replace	Not Given	X	SVC
	67004-47080	DOOR RR/LH	0.00	\$954.50	0.00	\$0.00	Replace	Not Given	X	
	61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X	
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X	
		STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X	
	61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	X	CR4
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X	
	81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	X	
	61602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Check	X	
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X	
		STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X	SVC
	65638-47021	FENDER LINER R/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X	
	61622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	X	
	52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X	
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Check	X	
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	CR4
	42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X	
	42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X	
	52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	X	
	52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	X	
	52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	X	Nec BR BR CR4 DD BT BT
	52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	X	
	52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace	X	
	52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80	Replace	Replace	X	
	57014-47030	ARM SUB-ASSY,FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace	X	
	57013-47030	ARM SUB-ASSY,FR BUMPER RH	1.00	\$250.40	25.00	\$187.80	Replace	Replace	X	SVC SVC CR4 CR4 DD
	53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Check	X	
	53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check	X	
	52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace	X	
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	X	
		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	X	CR4 CR4 CR4 CR4 CR4
	52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	X	
	52127-47903	COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	X	
	53102-47020	BUMPER GRILLE SUB-ASSY LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	X	
	82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given	X	
	88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Check	X	SVC
	81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check	X	
	81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check	X	

