



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Bldg D Singapore 417883
 Company & GST Registration No : 201828067M

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:
 Date:

VEHICLE INSPECTION ESTIMATE

M/S : India international Insurance Pte Ltd
 (MOTOR CLAIM DEPARTMENT)

Email motorclaim@iii.com.sg

Jasper

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SKM8841M Date: 29.03.2021
 Vehicle Model: HONDA CIVIC Reg. Date: 02.05.2018
 Chassis No: MRHFC1660HT000304 D.O.A: 24.03.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Bootlid <i>Dented</i>	1	\$ 785.60	\$ <u>785.60</u>	<i>572.80</i>
2	Bootlid Stoppers <i>New</i>	2	\$ 20.00	\$ 40.00	<i>+</i>
3	Bootlid Outer Garnish <i>Cracked</i>	1	\$ 298.60	\$ 298.60	<i>✓</i>
4	Bootlid Smartkey Antenna <i>2x4</i>	1	\$ 152.30	\$ 152.30	<i>+</i>
5	Bootlid Buzzer <i>Jam</i>	1	\$ 105.60	\$ 105.60	<i>+</i>
6	Bootlid Inner Trim <i>New</i>	1	\$ 215.60	\$ 215.60	<i>+</i>
7	Bootlid Emblem H <i>?</i>	1	\$ 89.70	\$ 89.70	<i>38</i>
8	Bootlid Emblem Civic <i>New</i>	1	\$ 78.50	\$ 78.50	<i>+ 58</i>
9	Bootlid Emblem V-Tec	1	\$ 73.60	\$ 73.60	<i>45</i>
10	Bootlid Lamp <i>2x4</i>	2	\$ 205.60	\$ 411.20	<i>+</i>
11	Bootlid Lamp Inner Seal <i>?</i>	2	\$ 38.00	\$ 76.00	<i>+</i>
12	Bootlid Lock <i>New</i>	1	\$ 169.50	\$ 169.50	<i>+</i>
13	Bootlid Latch <i>New</i>	1	\$ 46.20	\$ 46.20	<i>+</i>
14	Bootlid Hinges <i>New</i>	2	\$ 75.20	\$ 150.40	<i>+</i>
15	Bootlid Weatherstrip <i>cut</i>	1	\$ 179.20	\$ 179.20	<i>✓</i>
16	Rear Bumper <i>Deformed</i>	1	\$ 778.90	\$ <u>778.90</u>	<i>617.20</i>
17	Rear Bumper Retainers <i>New</i>	2	\$ 52.30	\$ 104.60	<i>48</i>
18	Rear Bumper Brackets <i>New</i>	2	\$ 45.60	\$ 91.20	<i>+</i>
19	Rear Bumper Lower Side Garnish <i>New</i>	2	\$ 69.70	\$ 139.40	<i>+</i>
20	Rear Bumper Side Reflectors <i>New</i>	2	\$ 59.80	\$ 119.60	<i>+</i>

C/F \$ 4,105.70



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
 Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

S/No.	Item Description	Qty	B/F Price	\$ 4,105.70 Total Cost	Surveyor Use
21	Rear Bumper Side Reflectors Covers <i>RH ut</i>	2	\$ 98.70	\$ 197.40	<i>-98.70</i>
22	Rear Bumper Reverse Sensor <i>1 piece damaged</i>	4	\$ 145.00	\$ 580.00	<i>-145</i>
23	Rear Bumper Reverse Sensor Holder <i>new</i>	4	\$ 36.00	\$ 144.00	<i>+</i>
24	Rear Bumper Sensor Wire Harness <i>new</i>	1	\$ 252.30	\$ 252.30	<i>+</i>
25	Rear Bumper Reinforcement <i>Dented</i>	1	\$ 305.80	\$ 305.80	<i>✓</i>
26	Taillamps <i>RH ut</i>	2	\$ 442.60	\$ 885.20	<i>368.</i>
27	Taillamp Inner Seal <i>new</i>	2	\$ 38.20	\$ 76.40	<i>-20.</i>
28	Taillamp Panel <i>Repair</i>	2	\$ 345.80	\$ 691.60	<i>+</i>
29	Rear Fender Inner Cowling <i>new</i>	2	\$ 156.20	\$ 312.40	<i>+</i>
30	End Panel <i>Dented</i>	1	\$ 578.40	\$ 578.40	<i>✓ 398.</i>
31	End Panel Top Garnish <i>cracked</i>	1	\$ 145.60	\$ 145.60	<i>✓</i>
32	End Panel Stoppers <i>new</i>	2	\$ 35.00	\$ 70.00	<i>+</i>
33	Spare Tyre Panel Top Board <i>new</i>	1	\$ 185.90	\$ 185.90	<i>+</i>
34	Spare Tyre Tool Sponge <i>new</i>	1	\$ 98.50	\$ 98.50	<i>+</i>
35	Rear Silencer Box RH <i>Repair</i>	1	\$ 750.20	\$ 750.20	<i>+</i>
36	Rear Silencer Box Mounting RH <i>new</i>	2	\$ 38.00	\$ 76.00	<i>+</i>
37	Rear Silencer Heat Shield RH <i>new</i>	1	\$ 119.80	\$ 119.80	<i>+</i>

Total For List Items: \$ 9,575.20
Less Spare Parts Discount (10%): \$ 957.52
Total: \$ 8,617.68
C/F \$ 8,617.68

3337-90
2670-32



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
 Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 8,617.68

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Rear Bumper Centre Lower Garnish - Accessories <i>could</i>	1	\$ 680.00	\$ 680.00	<i>SW</i>
2	Rear Number Plate W Casing <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
3	Rear Bumper Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
4	Bootlid Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
5	End Panel Garnish Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
6	Rear Fender Inner Trim Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
7	Rear Fender Outer Cowling Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
8	Taillamp Clips <i>new</i>	2	\$ 30.00	\$ 60.00	<i>10</i>
9	Bootlid Lamp Clips <i>new</i>	2	\$ 30.00	\$ 60.00	<i>+</i>
10	End Panel Insulator Seals <i>new</i>	2	\$ 80.00	\$ 160.00	<i>60</i>
11	Rear Reverse Camera <i>new</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
12	Exhaust Pipe Muffler RH <i>at</i>	1	\$ 83.00	\$ 83.00	<i>✓</i>

Total For S/N Items: \$ 1,493.00

703

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To straighten/realign accident affected portion	1	\$ 1,500.00	\$ 1,500.00	<i>800</i>
2	To respray accident affected portion.	1	\$ 1,500.00	\$ 1,500.00	<i>1000</i>
3	To tuff coat affected areas	1	\$ 150.00	\$ 150.00	<i>60</i>
4	To remove/refix rear interior upholstery	1	\$ 120.00	\$ 120.00	<i>60</i>
5	To check wiring/wire connector and rewire/repair	1	\$ 100.00	\$ 100.00	<i>30</i>
6	To remove/refix reverse sensors and distance setting	1	\$ 150.00	\$ 150.00	<i>50</i>
7	To remove/refit/replace rear reverse camera	1	\$ 150.00	\$ 150.00	<i>50</i>
8	To remove/realign/replace exhaust pipe/silencer	1	\$ 200.00	\$ 200.00	<i>80</i>
9	To dismantle/transfer/repair bootlid components	1	\$ 150.00	\$ 150.00	<i>60</i>
10	To conduct water leakage testing	1	\$ 100.00	\$ 100.00	<i>+</i>

Total For Labour: \$ 4,120.00

2190

total: 5563.32
A/S: 4.4K.

Adrian
L/S 30/03/21
06 Days