

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD		Ref:	CS/LAW21003956/Aqf3e2	
		UTIONS LLC CE #44-05 UOB PLAZA 24SINGAPORE 189556		Date:	02/07/2021	
				Code:	INC3	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SGL 9716M	Veh. Inspected		SKT 1456B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	LIH/962157/NTUC	Excess (\$)		0.00	
	Assign From	LIM HUI YING	Assign Date		26/03/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ESTIMA	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	ACR500188296	Colour		GREY	
	Odometer	120037 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/50 R18	CONTINENTAL		6 mm	
	L/H Front Tyre	225/50 R18	CONTINENTAL		6 mm	
	R/H Rear Tyre	225/50 R18	CONTINENTAL		6 mm	
	L/H Rear Tyre	225/50 R18	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.					
	REPAIR CONDITION	ON SEE DETAILS.				
5.	General Information					
	Accident Date	12/06/2016	Inspection Date	е	24/05/2021	
	Survey held at	25 corporation walk sg 618428				
	Repairer	JEC AUTO SERVICE PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					

9 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: