



Your Ref : SNM21D200874/C01/TANKL

Date: 11th June 2021

Our Ref : CS/CTI21003959/Gtf3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLG 6983U
ACCIDENT ON 27/01/2021**

Instruction was received to inspect the vehicle Reg. No. SLG 6983U. The inspection was conducted on 29/03/2021 at the premises of M/s Auto Insure Pte Ltd, 6 Marsiling Lane, Singapore 739145.

The following vehicle information was recorded:

Registration Number	: SLG 6983U
Make/Model	: Toyota Vios E Auto
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: MR053HY9305060883
Engine Capacity	: 1497 cc

The vehicle sustained damages at the o/s, n/s body, front, rear portion, undercarriage and rooftop. The body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 16,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 8,509.00)
Nett Liability	<u>S\$ 7,491.00</u> =====

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.