LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Tan Kah Leong Date: 06 Apr 2021

Preliminary Advice

Vehicle No : SLG6983U Accident Date : 27/01/2021

Make : TOYOTA VIOS Policy No. : DMPCSNW00147842004

Assignment Date : 26/03/2021 **Excess** : S\$500.00

Date of Inspection Est. Duration of Repair : 29/03/2021 : 0

Inspection At : AUTO INSURE PTE LTD (HQ) (WOODLANDS)

6 MARSILING LANE SINGAPORE 739145

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 16,000.00 COE / PARF Rebate(estimated) 8,509.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 7,491.00

Remarks

()	The vehicle is repairable at our adjusted amoun	t. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.	

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments: Vehicle has de-register