



KGC WORKSHOP PTE LTD

Sincere • Secure • Satisfaction



14 Ang Mo Kio St.63, Block B (S) 569116

Tel : 6453 6279 / 6456 5410

Email : contact@kgcworkshop.com.sg

Ho Soo Kit

14 Ang Mo Kio St 63

Block B

Singapore 569116

*Not within
11 Rm & 1200h
Penny Aka 1 day
2 days*

Date 1/6/2021

No of Page : 1/1

Registration No : SKC 3503A

Accident Date : 25-Mar-21

Our Ref : TP

Model : Mazda 3

Chassis No: JM6BM44A8G0307275

Engine Capacity 1496

S/No	Qty	Items	Unit Price	Amount
1	1	Front Door RHS	1,201.00 \$	1,201.00 ✓
2	1	Front Door weather strip RHS	\$ 125.80	125.80 X
3	1	Front Door Window Regulator RHS	\$ 225.30	225.30 X
4	1	Front Door-applique RHS	\$ 72.50	72.50 X
5	1	Front Door Moulding RHS	\$ 80.40	80.40 X
6	1	Front Door Inner Trim Board RHS	\$ 889.80	889.80 X
7	1	Front Fender RHS	\$ 558.20	558.20 X
			\$	3,153.00
			-20%	\$ 630.60
Total for spare parts			\$	2,522.40

Special Nett

1	1 set	LHS Front Inner Trim Board Clip	\$ 5.00	\$ 50.00 X
Total for SP			\$	50.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.		800.00 200
2		To putty and spray paint on all accident damage parts and other accident affected areas		600.00 220
3		To check wiring system to facilitate repair and refit the same		100.00 20
4		Apply rust proofing on the adjacent panels		80.00 30
5		Transfer door mechanism		150.00 60
6		to conduct Water Proof Test		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

TOTAL AMOUNT : 50.00 X
OVERALL COST : 1,780.00
4,352.40