



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CHAN KIAN CHUAN

Ref: CC4/ASM21003965/Gba3q2
Date: 04/10/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2437E	Veh. Inspected	EM 9898P
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S1M035W0	Excess (\$)	0.00
Assign From		Assign Date	26/03/2021

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 530I	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBAJA52080WC08622	Colour	WHITE
Odometer	33548 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/30Z R20	PIRELLI	6 mm
L/H Front Tyre	275/30Z R20	PIRELLI	6 mm
R/H Rear Tyre	275/30Z R20	PIRELLI	6 mm
L/H Rear Tyre	275/30Z R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/03/2021	Inspection Date	26/03/2021
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**