

BIFROST AUTO

8 KAKI BUKIT AVE #01-49, PREMIER @ KAKI BUKIT
SINGAPORE 415875

Estimate for EM9898P (BMW 530i)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty Spare Parts

List Price (\$)

1	Rear bumper	\$	1,844.50
1 set	Rear bumper clips	\$	70.00
1	Rear bumper LH side retainer	\$	78.10
1	LH rear fender		Repair
1	LH rear shock absorber	\$	578.30
1	LH rear lower arm	\$	988.10
1	LH rear wheel bearing	\$	425.00
1	LH rear knuckle arm	\$	903.70
1	LH rear upper arm	\$	424.00
1	LH rear control arm	\$	543.00
		\$	5,854.70
		-5% \$	292.74
		\$	5,561.97

Qty Spare parts

Special Nett (\$)

1	LH rear sport rim	\$	1,500.00
1	LH rear tyre	\$	550.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$	800.00	200
Spray painting on affected panels	\$	800.00	400
Check wiring and lighting system	\$	50.00	X NN
Conduct, adjust and test drive wheel alignment system	\$	100.00	60
Remove and replace rear undercarriage parts	\$	350.00	?
Remove and reinstall rear bumper reverse sensors	\$	80.00	40

Total: \$ 9,791.97

3 Days -
unpainted repair
After repair photos
Gme @ 10p
26/3/21