

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0116/2021/KS
DATE : 4-Feb-21
WIP : 14280

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED YUAN JI ENTERPRISES PTE LTD**

Yuan Ji Enterprises Pte Ltd
AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

8 days exclude 1 Sunday

Johnny Boo 14 Jul 21

OWNER'S NAME : LIM SIEW HWA
ADDRESS : 80 JELlicoe ROAD
#11-02
SINGAPORE 208766
TELEPHONE : HP +65 91397695
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100443165-04
VEHICLE NO : **SKX 5508 M**
MODEL CODE : A3 SPORTSBACK 1.4 TF
MODEL YEAR : 17/12/2015
ENGINE NO : CZC 501632
CHASSIS NO : WAUZZZ8V7GA067472
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Feb-21
PLACE OF ACCIDENT : Near 114 Lavender St, Singapore 338729

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKX 5508 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	360.00	\$	360.00
2	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL/ RENEW LHS WING MIRROR ASSY.	S/N \$	280.00	\$	280.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$	3,150.00	\$	2,000.00
4	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLES, LHS REAR DOOR AND LHS REAR FENDER.	\$	5,400.00	\$	3,350.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	na	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$	9,942.00	\$ 6,462.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5508 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,016.00	\$	1,612.80
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00		
3	FRONT BUMPER COVER LOWER CENTRE	1	\$ 156.00		
4	FRONT BUMPER LOWER PULL STRAP	4	\$ 206.00		
5	FRONT BUMPER GUIDE SECTION LH	1	\$ 63.00		
6	FRONT BUMPER AIR GUIDE GRILLE	1	\$ 109.00	\$	87.20
7	RADIATOR GRILLE	1	\$ 691.00		
8	RADIATOR GRILLE COVER	1	\$ 98.00		
9	FRONT BUMPER REINFORCEMENT	1	\$ 795.00		
10	FRONT BUMPER IMPACT ABSORBER	1	\$ 83.00		
11	FRONT SUPPORT PANEL TOP COVER	1	\$ 56.00		
12	FRONT FENDER LH	1	\$ 851.00	\$	680.40
13	FRONT FENDER ATTACHMENT PARTS LH	1	\$ 72.00		
14	FRONT FENDER TOP BRACKET LH - REAR	1	\$ 28.00	\$	21.84
15	FRONT FENDER TOP BRACKET LH - FRONT	1	\$ 48.00	\$	37.68
16	FRONT FENDER BRACE LH	1	\$ 96.00	\$	76.48
17	FRONT FENDER LOWER BRACKET LH	1	\$ 62.00	\$	48.88
18	FRONT WHEEL HOUSING LINER LH	1	\$ 169.00		
19	FRONT WHEEL HOUSING LINER ATTACHMENTS PARTS LH	1	\$ 89.00		
20	BONNET	1	\$ 2,745.00	\$	2,196.00
SUB TOTAL SPARE PARTS		:	\$ 8,620.00	\$	4,761.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5508 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f		\$ 4,761.28
21	BONNET ATTACHMENT PARTS	1	\$ 165.00	
22	BONNET EDGE PROTECTION SEAL - FRONT	1	\$ 28.00	\$ 22.00
23	BONNET STRIKER	1	\$ 110.00	
24	BONNET LOCK W/ MICRO SWITCH	1	\$ 214.00	
25	HEADLIGHT LH	1	\$ 2,641.00	\$ 2,112.80
26	HEADLIGHT WASHER LIFT CYLINDER LH	1	\$ 193.00	
27	WING MIRROR MOUNTING LH	1	\$ 1,024.00	
28	FRONT ALUMINIUM RIM LH	1	\$ 1,166.00	
29	SUNDRIES	1	\$ 400.00	\$ 45.60
30	FRONT NO. PLATE	S/N	\$ 60.00	
TOTAL SPARE PARTS			\$ 14,621.00	\$ 6,941.68
TOTAL LABOUR CHARGES			\$ 9,942.00	\$ 6,462.00
GRAND TOTAL			\$ 24,563.00	\$ 13,403.68

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-04/05/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT