



興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

P-1-3

MNetscape Landscaping

GBE 12394

Date

16/3/21

NO.

1.	Rear tail gate / DD	\$ 1217.45	/
2.	2 Rear tail gate hinges \$ 177.80 @ / BT.	\$ 355.60	/
3.	Rear No plate panel. / DD.	\$ 371.75	281
4.	Rear LH tail lamp Assy X / CRA	\$ 219.90	/
5.	Rear LH tail lamp panel / BT	\$ 272.10	185
6.	Rear LH Stopper Bracket / CRA / BT	\$ 78.10	/
7.	Rear LH Stopper Rubber "A" / CRA	\$ 121.10	75.50
8.	Rear LH Stopper Rubber "B" Xsvc	\$ 134.45	X
9.	Rear tail gate "TOYOTA" sticker / NEC	\$ 180.00	N79 S/N
10.	Rear tail gate "DYNA" sticker / NEC	\$ 158.20	/
11.	Rear end panel XR.	\$ 971.45	X
12.	Rear Exhaust XR	\$ 991.25	X
13.	Rear spare tyre holder ? / BT	\$ 371.75	/
14.	front panel. / DD	\$ 1387.75	950
15.	front "DYNA" emblem / NEC	\$ 138.20	72
16.	front logo / NEC	\$ 171.45	71.80
17.	front Grille / CRA	\$ 581.90	/
18.	1 Set front Grille clip / NEC S/N	\$ 35.00	/ SN
19.	1 front LH Head Lamp Assy ? Xsvc	\$ 932.40	X
20.	front panel garnish / SCR.	\$ 308.90	/
21.	front bumper / DD	\$ 441.60	/
22.	2 RXL front bumper Bracket \$ 231.34 @ ? Xsvc	\$ 462.68	X
23.	front windshield rubber. / NEC	\$ 358.10	303.70





bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996

TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

Pg-2

GRT 1239Y

Date 16/3/21 NO.

24	front Head Lamp Assy RH	1 CRA	\$ 932.40	✓
25	front Aircon Blower Housing	1 X SVC	\$ 978.20	X
26	front Aircon coil & Housing	1 X SVC	\$ 2332.10	X
27	Rear Strip Board	1 BT	\$ 450.00	SN 380.
				S/N
			6,574.80	494.
			-25%	
			4,931.10	





興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@pacific.net.sg

Pg.3

Masr's Cape Landa Caping

GBE1239Y

Date

16/3/21

NO.

	Labour Charge		
1.	To Remove & Refit front w/screan.	\$ 120.00	/
2.	To Remove & Replace front AirCo System n TO up gas.	\$ 160.00	1020
3.	To Remove & Refit front Instrumen panel.	\$ 320.00	200
4.	Wiring fee	\$ 50.00	30
5.	front no plate	\$ 40.00	/
6.	Rear no plate	\$ 40.00	/
7.	Rear taxi gate inner Cover Remove & Refit	\$ 120.00	60
8.	spray painting Damage area front & Rear	\$ 1400.00	1,100
9.	To Repair front & Rear Acc Damage Portion	\$ 1500.00	1,100
10.	Rear Exhaust Remove & Refit & Repair	\$ 120.00	60
11.	Rear "8 pax" Sticker	\$ 15.00	/
12.	Rear "70 km" Sticker	\$ 15.00	/
13.	front LH Door Add Sticker	\$ 25.00	/
			2,925

Repair day 7 days

L/S

After pan photo

Sun Pin (HKK)

30/03/2021

TP with pre-jud



18,848.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677998
TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@pacific.net.sg

Accd: JK Sun pin

Yassts Cape Lands Caping

GBE 1239 Y

Date 29/3/21 NO.

Supplementary.

1.	Rear LH tail gate Lock (side) / BT.	\$ 198.35	✓
2.	Rear 1 Set Sensor / short.	\$ 220.00	SN ✓
3.	front wiper panel. Cover. XR.	\$ 438.70	X
4.	front panel RH Garnish / CRA	\$ 571.75	95
5.	Air blower Air hose / def.	\$ 185.00	SN ✓
6.	Rear tyre Bracket Member / BT.	\$ 561.60	380
7.	front cross Member. / BT	\$ 443.32	✓
8.	Anti Rust	\$ 80.00	SN 40
9.	front Panel joint Sealant.	\$ 80.00	SN 50.
			S/N
		1,116.67	495
		- 25%	
		837.50	
	P = 4,931.10		
	Supp P = 837.50		
	S/N = 494		
	Supp SN = 495		
	L = 2,925		
	9,682.60	L15	
	- 20%	\$ 7,750	
	7,746.08	7 days	

