

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5659G**AAD2103-***Not Authoink**11 Sep 87,300.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

29 MAR 2021**SHC5659G**

VF1ABL15AUC279754

RENAULT

LATITUDE

25/03/2021

FCI

04/11/2014

PART		LIST	
1	BONNET	\$	<i>R</i> 1,312.70 <i>X</i>
1	DOOR MIRROR ASSY LH	\$	<i>CRF</i> 1,483.40 <i>✓</i>
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66 <i>✓</i>
1	DOOR MOULDING FRT LH	\$	<i>S</i> 100.50 <i>X</i>
1	DOOR FINISHER FRT LH	\$	<i>S</i> 258.90 <i>X</i>
1	DOOR HANDLE OUTER FRT LH	\$	<i>R</i> 169.50 <i>X</i>
1	DOOR HANDLE MODULE FRT LH	\$	<i>S</i> 133.40 <i>X</i>
1	DOOR REGULATOR FRT LH	\$	501.40 <i>?</i> SVR
1	DOOR REGUALTOR MOTOR FRT LH	\$	758.10 <i>?</i> SVR
1	DOOR HINGE UPPER FRT LH	\$	<i>R</i> 274.50 <i>X</i>
1	DOOR HINGE LOWER FRT LH	\$	<i>R</i> 300.55 <i>X</i>
1	DOOR WEATHERSTRIP FRT LH	\$	<i>CRF</i> <i>S</i> 316.00 <i>Golden</i>
1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66 <i>✓</i>
1	DOOR REGULATOR REAR LH	\$	<i>R</i> 450.60 <i>X</i>
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>S</i> 758.10 <i>X</i>
1	DOOR HANDLE OUTER REAR LH	\$	<i>S</i> 42.10 <i>X</i>
1	DOOR HANDLE MODULE REAR LH	\$	<i>S</i> 133.40 <i>X</i>
1	DOOR HINGE UPPER REAR LH	\$	<i>R</i> 241.60 <i>X</i>
1	DOOR HINGE LOWER REAR LH	\$	<i>R</i> 169.90 <i>X</i>
1	DOOR WEATHERSTRIP REAR LH	\$	<i>S</i> 311.60 <i>X</i>
1	ROCKER PANEL OUTER LH	\$	<i>R</i> 1,184.99 <i>X</i>
1	FENDER PANEL FRT LH	\$	<i>R</i> 437.10 <i>✓</i>
1	WHEELARCH FRT LH	\$	<i>S</i> 191.40 <i>X</i>
1	FENDER PANEL REAR LH	\$	<i>R</i> 1,933.20 <i>X</i>
1	WHEELARCH REAR LH	\$	<i>S</i> 275.40 <i>X</i>
1	BUMPER COVER REAR	\$	<i>R</i> 561.70 <i>X</i>
TOTAL		\$	16,676.66

Trans-cab Auto Services Pte Ltd

AAD2103-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5659G

10% \$ 1,667.67

Over All Total \$ 15,008.99

Special Nett

1	REAR BUMPER CLIP	\$	na	65.00	X
1	REAR FENDER CLIP	\$	na	70.00	X
1	DOOR TRIM CLIP	\$	na	70.00	X
1	DOOR MOULDING CLIP	\$	na	70.00	X
1	DOOR STICKER TRANSCAB	\$	na	100.00	60sn
1	DOOR STICKER 65553333	\$	na	100.00	60sn
1	DOOR STICKER CLASSIC	\$	na	100.00	15sn
2	WINDSCREEN SEALANT	\$	na	150.00	X
1	WINDSCREEN MOULDING	\$	na	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
TOTAL		\$		1,055.00	

TOTAL PARTS \$ 16,063.99**LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	90%
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	12%
Putty and spray painting of the affected portion.	\$	1,400.00	115%
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	60%
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	20%
To check steering geometry and computer wheel alignment	\$	na	220.00 X
TOTAL	\$	4,360.00	

Trans-cab Auto Services Pte Ltd

AAD2103-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5659G

Over All Total \$ **20,423.99**

(LUMPSUM) Repair Days

~~28~~ Days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: