



3 of 3

Report No. T/20201016/2091

Police Station Of Origin: Woodlands East N.P.C. 3 Woodlands Drive 63 SINGAPORE 737890

Tel No: 1800-7679999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have
the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

Insp DALY CHIN JUN CHANG

Signature Of Interpreter: Not applicable

Officer In Charge Of Case: TP / AEIT / SSI 2 JUREMAH BINTE AHMAD Contact No.: 65476219

Authentication Stamp

Signature Of Informant:

Date/Time:

16/10/2020 20:19

Classification Of Case:

SN 130

Singapore Police Force

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands (S) 757322

Tel: 63397378/86606722

Fax: 63397475

Reg No: 201700196D GST Reg No: 201700196D

PI - 102952 91

Date: 28/02/2021

OUR REF: TP/SLN 7434U/21

M/S: GNANASEGARAN S/O RAMALINGAM

BLK 861 WOODLANDS ST 83

#06-166

SINGAPORE 760861

Statement Of Claim On Veh No : SLN 7434U MODEL: HONDA VEZEL

LUMP SUM OF REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

\$8,300.00

7% **GST**

\$581.00

\$8,881.00

ZACH CARS LEASING PTE. LTD.

280 Woodlands Industrial Park E5 #01-18 Harvest@Woodlands (S) 757322 HP: 9388 2885/8660 0722 Tel: 6339 7378 Fax: 6339 7475 Email: zach.cars@yahoo.com Reg. No: 201922178R

-RENTAL AGREEMENT NO.: 00220 -VEHICLE REG. NO: SMP5079C	ription Amoun	lo
-RENTAL PERIOD : 26/10/2020 TO 02/11/2020 (7DAYS)	\$ 840.	RENTAL -RENTAL AGREEMENT NO.: 00220 -VEHICLE REG. NO: SMP5079C -MAKE AND MODEL: MAZDA 2

S LEASING S 201922178H m

PAYABLE AMOUNT \$

840.00

ZACH CARS LEASING PTE LTD

Customer Signature & Company Stamp


ZACH CARS LEASING PTE LTD 9LN 74344


280 Woodlands Industrial Park E5 #01-18 Harvest @ Woodlands (S) 757322

HP: 93882885/86600722 Rental Agreement

No.: 00220

Name: GN ANASEGARAS SI	Driving Licence Pass Date: 20 (07/84)
IC or Passport No.: S 364 3867	E Address: BIK 861 Woodlands 87 83 # 06-166
Tel (HP): 83102237	(s) 760861.
DRIVER'S PARTICULARS	
Name:	Driving Licence Pass Date:
IC or Passport No.:	Address:
Tel (HP):	





The vehicle has a full tank of fuel when picked up and must be returned in full. If not, the renter is responsible for the actual refuel plus a service fee of \$50.00

		1110	ii Oitiiriidi id	91201		1			CHARGES	
1.		ce Coverage if the	e driver is below 22	yrs old or less than 2 years dr	iving	1			CHARGES	
2.		is licenced to ca		passengers only.	7	Day	at \$	120	per day	\$ 840.00
3.		le to pay first \$ ing while damag	ed vehicle is under	as excess all claim any accide repair.	ent plus	Day	at \$		per month	101
4.				all claims of S\$5,000.00 and d	ifferent	Day	at \$		per week	
5.	Please notif			ident involving this hired with	in 24 hrs.					
6.			ehicle returned earl							
8.			etrol left in vehicle, ing fee and traffic s			-				
9. 10.	Vehicles to		office hours only.	ullinonses.		TOTAL	AMC	UNT		\$840.00 \$840.00
10.	No service	on russic nostuay	y and ounday						and the same of th	L 0.1. 00
	SCHEDU	LE		MO	DEL	AMOL	JNT P	AID		\$840.00
31	mp 5	679c		Mardo	12	BALAI	NCE D	UE		
	Date		Time	Milea	ge					
7	26/10	20	1:100	m			malli	at Dono	sit (refundable) \$	
	2/11/		1: wp	The same of the sa						
1/W	e have	read and u	inderstood	the terms and con	ditions	above	and I	nereby a	agreed to abide	

Renter Signature

Driver Signature

24 Penshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

INVOICE

Invoice No:

CL/200547

Gnanasegaran S/O Ramalingam

C/o: Elite Automotive Pte Ltd

280 Woodlands Industrial Park E5 #01-17

Harvest @ Woodlands, Singapore 757322

Ref No:

EAPL/10/2002/TP

Date:

12 November 2020

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SLN 7434 U
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 706.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CLAPPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Gnanasegaran S/O Ramalingam

Date

: 12 November 2020

C/o: Elite Automotive Pte Ltd

Our ref

: EAPL/10/2002/TP

280 Woodlands Industrial Park E5 #01-17

Harvest @ Woodlands, Singapore 757322

Accident Date

: 16 October 2020

Type of Survey

: Third Party

Inspection Date : 26 October 2020

Repairer Name

: Elite Automotive Pte Ltd

280 Woodlands Industrial Park E5 #01-17

Harvest @ Woodlands, Singapore 757322

PARTICULARS OF VEHICLE

Registration No : SLN 7434 U

Year / Capacity

: 2017 / 1496 cc

Make / Model

: Honda Vezel

Colour

: Bronze

Chassis No

: RU31237000

Mileage

: 185965

Engine No

: LEB5937013

CONDITION OF TYRES

		Make	Size	Thread Balance	Rim
Front Nearside	:	Toyo	215/60 R16	5 mm	Sport
Front Offside	:	Toyo	215/60 R16	5 mm	Sport
Rear Nearside	:	Toyo	215/60 R16	5 mm	Sport
Rear Offside	:	Toyo	215/60 R16	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion. (Details refer to the photographs attached)

Enclosed number of photographs:

86

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$ 8,300.00 on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.



Vehicle Registration No: SLN 7434 U Our Ref No: EAPL/10/2002/TP

Qty	Description	Conditions	Repairer's Estimate		Revised
			Estimate		Amount
	SPARE PARTS - LIST ITEMS				
1	Front bonnet	Damage	\$ 1,151.70	\$	1,151.70
2	Front bonnet hinges	Necessary	\$ 143.40	\$	143.40
1	Front bonnet rubber	Necessary	\$ 78.30	\$	78.30
1	Front n/s headlamp	Damage	\$ 1,784.50	\$	1,784.50
2	Front headlamp lower brackets	Damage	\$ 150.60	\$	150.60
1	Front grille	Damage	\$ 285.00	\$	285.00
1	Front grille top outer garnish	Damage	\$ 225.00	\$	225.00
1	Front grille logo	Necessary	\$ 45.70	\$	45.70
1	Front bumper	Damage	\$ 1,085.40	\$	1,085.40
1	Front bumper centre grille	Damage	\$ 167.00	\$	167.00
1	Front bumper n/s fog lamp	Damage	\$ 327.70	\$	327.70
1	Front bumper n/s fog lamp cover	Damage	\$ 45.20	\$	45.20
1	Front bumper reinforcement	Damage	\$ 321.40	\$	321.40
1	Front bumper reinforcement stay	Damage	\$ 155.00	\$	155.00
2	Front bumper side retainers	Necessary	\$ 120.60	\$	120.60
2	Front fenders	N/S Damage	\$ 1,160.80	\$	580.40
1	Front n/s fender emblem	Necessary	\$ 55.00	\$	55.00
1	Front n/s fender wheel arch garnish	Damage	\$ 488.30	\$	488.30
1	Front support panel	Damage	\$ 576.00	\$	576.00
1	Front support panel top garnish	Damage	\$ 90.30	\$	90.30
2	Front support panel side garnishes	Damage	\$ 141.00	\$	141.00
1	Front n/s door	Repair	\$ 1,085.70		
1	Front n/s wheel rim	Repair	\$ 650.00		
		on	\$ 10,333.60	\$	8,017.50
		Less 20%	\$ 2,066.72	\$	1,603.50
	Total Cost - List Items	u.=	\$ 8,266.88	\$	6,414.00
	SPECIAL NETT ITEMS				
	Front bumper clip (1 set)	Necessary	\$ 45.00	\$	45.00
1	Front bumper lower spoiler	Damage	\$ 750.00	\$	750.00
	Total Cost - Special Nett items		\$ 795.00	\$	795.00

Total cost of parts

\$	9,061.88	\$	7,209.00
----	----------	----	----------



Vehicle Registration No: SLN 7434 U

Our Ref No: EAPL/10/2002/TP

S/No	Description	Repairer's Estimate			Revised Amount		
	Total cost of parts c/f	\$	9,061.88	\$	7,209.00		
	<u>LABOUR</u>						
1	To check wiring, lighting and resetting headlamps focussing.	\$	80.00	\$	50.00		
2	To conduct wheel alignment.	\$	150.00	\$	120.00		
3	To remove and refit air-con condenser, vacuum, refill gas and conduct leakage test.	\$	180.00	\$	120.00		
4	To apply undercoating on repaired and replaced panel.	\$	150.00	\$	90.00		
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,800.00	\$	1,500.00		
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,600.00	\$	1,320.00		
	GRAND TOTAL	\$	13,021.88	\$	10,409.00		



Vehicle Registration No: SLN 7434 U

Our Ref No: EAPL/10/2002/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$8,300.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser



