



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21004001/Qqf3q2 Date: 06/04/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GW 8893H	Veh. Inspected	SG 5306Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024332	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	29/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO B9TL 9.4L	c.c	9364	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	YV3S4P929GA176027	Colour	MULTI COLOUR	
Odometer	334818 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
R/H Rear Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
L/H Rear Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2021	Inspection Date	30/03/2021	
Survey held at	3 Yio Chu Kang Crescent road			
Repairer	SBS TRANSIT LTD (HQ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	