



CYCLE & CARRIAGE

AIG - OD REVERT
Survey: STEVE

VEHICLE NO : SMN 5009 R

MODEL : KIA/ STINGER 2.0

WIP : 31187

Material	:	\$	<u>875.20</u>
Labour	:	\$	<u>1,700.00</u>
Sub-Total	:	\$	<u>2,575.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>2,575.20</u>
GST 7%	:	\$	<u>180.26</u>
Grand Total	:	\$	<u>2,755.46</u>
Finalise By/Date : <u>Larry ON 06/04/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk. end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 29/03/2021	Cust No/Name	/Mr Ong
	Reg No/Reg Date	SMN5009R / 24/08/2018
	Date In/Mileage	29/03/2021/ 0
	Chassis/Package	KNAE351AMJ6036905 /KC17P
	Engine No	G4KLJH016203
	Make/Model	KIA/STINGER 2.0 A834RED LEATHER
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/04/2021/ 17:19	BLC	884 / Lauro Songcuan	31187

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M-SUNDRY				20.00 ✓
SUNDRIES				
E PNT88000				400.00 ✓
RENEW REAR BUMPER, REPAIR BOOTLID, REAR SPOILER				
E PNT98000				1050.00 ✓
SPRAY PAINT FOR REAR BUMPER, BOOTLID GARNISH, REAR SPOILER				
E PNT88000				80.00 ✓
REMOVE & INSTALL PARKING SENSOR				
A 90000001				30.00 ✓
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				
A 10028901				120.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				
USING HI-SCAN PRO TEST				
X COVER-RR BUMPER ✓	1.00	639.00	20.00	511.20 ✓
X COVER-RR BUMPER LWR ✓	1.00	342.00	20.00	273.60 ✓
X EMBLEM-STINGER ✓	1.00	68.00	20.00	54.40 ✓
X EMBLEM-GT LINE ✓	1.00	45.00	20.00	36.00 ✓
Z TEXT				
OD CLAIM AIG - TP NTUC				
DOA: 27/03/2021				
SURVEY: STEVE (LKK)				
04 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	875.20	Nett	2,575.20
Labour	1,680.00	7% GST on	180.26
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	2,755.46
Sundry/Others	20.00		
Total(w/o GST)	2,575.20		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



HOME

Online



Stinger(CK)/2018/G 2.0 T-G..



VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



PTG



ICU



CLU

20/20

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESHIFTER	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
IBU-SMK	B16AB00	Rear Bumper Antenna Failure	Active

S/W Ver.

M-E-K-01-00-0242

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0183

OS Ver.

Android 10

HOME
 Online
Stinger(CK)/2018/G 2.0 T-G..
VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

PTG
 ICU
 CLU

20/20

System	Status	Result
RVM	No Current DTC	Good
AHLS	No Current DTC	Good
AHS	No Current DTC	Good
DDM	No Current DTC	Good
HUD	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
IBU-SMK	B16AB00	Rear Bumper Antenna Failure	Active

S/W Ver.	M-E-K-01-00-0242	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0183	OS Ver.	Android 10



HOME

Online



Stinger(CK)/2018/G 2.0 T-G..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



PTG



ICU



CLU

20/20

System	Status	Result
HUD	No Current DTC	Good
IBU-BC M	No Current DTC	Good
IBU-SM K	DTC Found.	Fault(01)
IBU-TP MS	No Current DTC	Good
PSM	No Current DTC	Good
SCM	No Current DTC	Good

System	DTC	Description	State
IBU-SMK	B16AB00	Rear Bumper Antenna Failure	Active

S/W Ver.

M-E-K-01-00-0242

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0183

OS Ver.

Android 10