



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



GST Reg No : MR-8500111-X

Co Reg No : 199405410K

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr Ong YONG HONG Blk 25 Fernvale Close #16-14 Singapore 797462 Contact No Mobile: 97774898	Cust No/Name /Mr Ong Reg No/Reg Date SMN5009R / 24/08/201 Date In/Mileage / 0 Chassis No KNAE351AMJ6036905 Engine No G4KLJH016203 Make/Model KIA/STINGER 2.0 AB34RED LEATHER Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
CSM00081	Cash	29/03/2021/ 13:06	BLC	442 / CocoLu	31187				
Description of Goods / Services									
M SUNDRY									20.00
Sundry									
E PNT88000									800.00
RENEW REAR BUMPER, REAR SPOILER, REPAIR BOOTLID,									1050 1440.00
E PNT98000									100.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR SPOILER									80 100.00
E PNT88000									30.00
REMOVE & INSTALL PARKING SENSOR									120.00
A 90000001									
CHECK WIRING & ELECTRICAL SYSTEM									
A 10028901									40.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST									
USING HI-SCAN PRO TEST									
M SUNDRY									639.00
C&C LOGO						1.00	639.00	00.00	639.00
M COVER-RR BUMPER						1.00	342.00	00.00	342.00
M COVER-RR BUMPER LWR						1.00	216.00	00.00	216.00
M TRIM ASSY-TAIL, LH						1.00	93.00	00.00	93.00
M MOULDING ASSY-RR BUMPER, CTR						1.00	29.00	00.00	29.00
M LAMP ASSY-REAR R/REFL, RH						1.00	29.00	00.00	29.00
M LAMP ASSY-REAR R/REFL, LH						1.00	189.00	00.00	189.00
M ULTRASONIC SENSOR ASSY-BWS						1.00	189.00	00.00	189.00
M ULTRASONIC SENSOR ASSY-BWS						1.00	64.00	00.00	64.00
M BRACKET ASSY-RR BUMPER SIDE, RH						1.00	64.00	00.00	64.00
M BRACKET ASSY-RR BUMPER SIDE, LH						1.00	85.00	00.00	85.00
M STAY-RR BUMPER LH						1.00	85.00	00.00	85.00
M STAY-RR BUMPER RH						1.00	263.00	00.00	263.00
M BEAM-RR BUMPER						1.00	79.00	00.00	79.00
M ANTENNA ASSY-SMARTKEY						1.00	212.00	00.00	212.00
M MOULDING-BACK PANEL						1.00	68.00	00.00	68.00
M EMBLEM-STINGER						1.00	45.00	00.00	45.00
M EMBLEM-GT LINE						1.00	554.00	00.00	554.00
M SPOILER-RR						1.00			

Estimate

Steve (LKK)

OD-MM AL

EXTRA - ?

P/P

My BL SM

4 days

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory and company stamp

7% GST on **Nett** 5,795.00
405.65
Total Payable 6,200.65

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date: