



Accident Reference & Bus No: E/1316/2021 - SBS8518Y

Activated date: Thu 3/25/2021 10:05 PM

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Estimate for

| Stock Code | Description | Quantity | Total Material cost(\$) | |
|------------|--|----------|-------------------------|-----|
| | | 0 | \$0.00 | C |
| 30541740 | LED INDICATOR LAMP | 1 | \$98.00 | ca- |
| 30541669 | REFLEX REFLECTOR | 1 | \$1.00 | ar- |
| 30311401 | BUMPER.REAR.F/G | 1 | \$170.00 | ca- |
| 30122005 | GAS JACK 0400N;RR ENG DOOR | 2 | \$52.00 | bt- |
| 30541741 | LED REVERSE LAMP | 1 | \$101.00 | ca- |
| 90082256 | STKR 60KM/H | 1 | \$0.00 | ca- |
| 90082270 | STKR SBS TRANSIT RR SD/DD | 1 | \$6.00 | bt- |
| 30541739 | LED TAIL/STOP LAMP | 1 | \$92.00 | ca- |
| 30122227 | ATTACHMENT BRACKET MID;RR FRAME | 1 | \$133.00 | bt- |
| 30122020 | COMPARTMENT HINGE RHS;RR DR | 1 | \$122.00 | bt- |
| 30122138 | INSULATION HOLDER 03;1.0MM ALUM SHEET | 10 | \$371.00 | bt- |
| 30122333 | INSERT @ RR FRAME BOTTOM;RR FRAME | 2 | \$46.00 | ca- |
| 30122145 | ALUM WIRE MESH;ENG DR;1PC=1.8M | 1 | \$172.00 | bt- |
| 30122129 | INSULATION 01;CPSS25;25MMX1MX2M;WIRING | 1 | \$149.00 | ca- |
| 30122019 | COMPARTMENT HINGE LHS;RR DR | 1 | \$122.00 | bt- |
| 30122158 | ATTACHMENT BRACKET BOTTOM;RR FRAME | 1 | \$57.00 | bt- |
| 30122484 | ENGINE REAR VENT COVER | 1 | \$65.00 | bt- |
| 30122036 | REAR DOME;F/GLASS;A&B SERIES | 1 | \$1,425.00 | ca- |
| 30122017 | DOOR FRAME;ENG COMPARTMENT DR;ALUM | 1 | \$325.00 | bt- |
| 30122018 | REAR DOOR;F/GLASS | 1 | \$350.00 | ca- |
| 30122627 | REPAIR KIT 4.PILLAR | 1 | \$45.00 | ca- |
| 38501048 | LATCH HOOK;FRT GRILLE PANEL;CL | 2 | \$11.00 | bt- |
| 53113129 | A/C COMPR C/W CL. SN A&B QV2.DENSO | 1 | \$1,864.00 | bt- |

Parts cost: \$ 5777.00

- Parts cost: 5777.00 ✓
 - Contractor Labour cost: \$ 4200 +gst ✓
 - Repair period: 10 day
 - Tow Cost: \$ 0
-

Tanpin 47495749
24/3/21 02:50pm
COR not finalise with w/s
10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: