

8 Kaki Bukit Ave 4 #08-45/46 Premier@ Kaki Bukit S415875
Tel: 6702 1555 Fax: 6702 1444 ROC No.: 201500047H

ESTIMATE

| | | | |
|------------------------|---|------------------------|---------------------|
| TO | : CHINA TAIPING INSURANCE | DATE | : 26-Mar-2021 |
| ATTENTION | : MOTOR CLAIM DEPARTMENT | JOB TYPE | : THIRD PARTY CLAIM |
| <u>VEHICLE DETAILS</u> | | <u>ACCIDENT DETAIL</u> | |
| VEHICLE NO. | : SGQ1152R | DATE | : 21-Mar-2021 |
| MAKE / MODEL | : MITSUBISHI OUTLANDER | TIME | : 18:25 hr |
| CHASSIS NO. | : JMYXTGF3WFZ001041 | | |
| OWNER INSURANCE | : AXA INSURANCE | | |
| POLICY NO. | : GA410554/1 | | |
| PERSON INCHARGE | : Falcoe T: 6702 1555 F: 6702 1444 falcolee@skauto.com.sg | | |

CLAIM DETAIL : LIST PRICE (\$S)

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|--|-----|-----------------|------------------|
| 1 | Rear Bumper <i>Dented</i> | 1 | \$ 930.00 | \$ 930.00 |
| 2 | Rear Bumper Lower Garnish <i>Dented</i> | 1 | \$ 430.00 | \$ 430.00 |
| 3 | Rear Bumper Side Garnish LH / RH <i>LH cut</i> | 2 | \$ 105.00 | \$ 210.00 |
| 4 | Rear Bumper Side Retainer LH / RH <i>new</i> | 2 | \$ 16.00 | \$ 32.00 |
| 5 | Rear Bumper Reinforcement Bracket LH / RH <i>new</i> | 2 | \$ 68.00 | \$ 136.00 |
| 6 | Rear Bumper Reflector Lamp LH / RH <i>LH cut</i> | 2 | \$ 155.00 | \$ 310.00 |
| 7 | Tailgate <i>Dented</i> | 1 | \$ 945.00 | \$ 945.00 |
| 8 | Tailgate Damper LH / RH <i>new</i> | 2 | \$ 225.00 | \$ 450.00 |
| 9 | Tailgate Hinges LH / RH <i>new</i> | 2 | \$ 45.00 | \$ 90.00 |
| 10 | Tailgate Weatherstrip <i>cut</i> | 1 | \$ 215.00 | \$ 215.00 |
| 11 | Tailgate Centre Garnish <i>cracked</i> | 1 | \$ 738.00 | \$ 738.00 |
| 12 | Tailgate "MITSUBISHI" Logo Badge <i>green</i> | 1 | \$ 55.00 | \$ 55.00 |
| 13 | Tailgate "OUTLANDER" Emblem | 1 | \$ 88.00 | \$ 88.00 |
| 14 | Tailgate License Plate Lamp LH / RH <i>new</i> | 2 | \$ 45.00 | \$ 90.00 |
| 15 | Taillamp LH / RH <i>cut RH, cracked LH.</i> | 2 | \$ 635.00 | \$ 1,270.00 |
| 16 | Tailgate Lamp LH / RH <i>cut LH, RH cracked</i> | 2 | \$ 554.00 | \$ 1,108.00 |
| 17 | Tailgate Wiper Motor <i>Dented</i> | 1 | \$ 490.00 | \$ 490.00 |
| 18 | Tailgate Wiper Motor Bracket <i>new</i> | 1 | \$ 45.00 | \$ 45.00 |
| 19 | Tailgate Wiper Arm <i>new</i> | 1 | \$ 76.00 | \$ 76.00 |
| 20 | Tailgate Wiper Bracket <i>cracked</i> | 1 | \$ 44.00 | \$ 44.00 |
| 21 | Rear LH Ventilator Duct <i>new</i> | 1 | \$ 55.00 | \$ 55.00 |
| 22 | Tailgate Windscreen Fastener LH / RH <i>new</i> | 2 | \$ 25.00 | \$ 50.00 |

807.
292
105
155.
820

| | | | | | |
|----|--|---|-------------|----------------------|---|
| 23 | Tailgate Windscreen Stopper LH / RH <i>Not New</i> | 2 | \$ 25.00 | \$ 50.00 | + |
| 24 | Tailgate Windscreen Top Moulding <i>New</i> | 1 | \$ 44.00 | \$ 44.00 | ✓ |
| 25 | Tailgate Windscreen Side Moulding LH / RH <i>New</i> | 2 | \$ 36.00 | \$ 72.00 | ✓ |
| 26 | Tailgate Lock Mechanism <i>Dented</i> | 1 | \$ 488.00 | \$ 488.00 | + |
| 27 | Tailgate Striker <i>New</i> | 1 | \$ 48.00 | \$ 48.00 | + |
| 28 | Tailgate Lock Outer Release Handle <i>New</i> | 1 | \$ 228.00 | \$ 228.00 | + |
| 29 | Tailgate Power Motor <i>Not New</i> | 1 | \$ 1,300.00 | \$ 1,300.00 | + |
| 30 | Tailgate Upper Stopper LH / RH <i>3 New</i> | 2 | \$ 21.00 | \$ 42.00 | + |
| 31 | Tailgate Lower Stopper LH / RH <i>3 New</i> | 2 | \$ 21.00 | \$ 42.00 | + |
| 32 | Tailgate Power Close Switch <i>New</i> | 1 | \$ 86.00 | \$ 86.00 | + |
| 33 | Tailgate Side Sensor Lock LH / RH <i>New</i> | 2 | \$ 488.00 | \$ 976.00 | + |
| 34 | Tailgate Inner Trim Board <i>Not New</i> | 1 | \$ 325.00 | \$ 325.00 | + |
| 35 | Tailgate Inner Trim Board Plug Cover <i>Not New</i> | 1 | \$ 58.00 | \$ 58.00 | + |
| 36 | Tailgate Inner Pull Handle <i>New</i> | 1 | \$ 38.00 | \$ 38.00 | + |
| 37 | Tailgate Inner Upper Trim LH / RH <i>3 All</i> | 2 | \$ 98.00 | \$ 196.00 | + |
| 38 | Tailgate Inner Upper Trim Centre <i>3 New</i> | 1 | \$ 310.00 | \$ 310.00 | + |
| 39 | Rear Keyless Operation Buzzer <i>Not New</i> | 1 | \$ 96.00 | \$ 96.00 | + |
| 40 | Rear Keyless Operation Antenna <i>Not New</i> | 1 | \$ 119.00 | \$ 119.00 | + |
| 41 | Rear End Panel <i>Dented</i> | 1 | \$ 257.00 | \$ 257.00 | ✓ |
| 42 | Rear End Panel LH / RH <i>Repair</i> | 2 | \$ 175.00 | \$ 350.00 | + |
| 43 | Rear End Panel Top Garnish <i>cut</i> | 1 | \$ 144.00 | \$ 144.00 | ✓ |
| 44 | Rear Cargo Floor Box <i>3 New</i> | 1 | \$ 226.00 | \$ 226.00 | + |
| 45 | Rear Cargo Floor Box Lid <i>3 New</i> | 1 | \$ 298.00 | \$ 298.00 | + |
| 46 | Rear End Panel Bumper Bracket Centre <i>3 All</i> | 1 | \$ 38.00 | \$ 38.00 | + |
| 47 | Rear End Panel Bumper Bracket LH / RH <i>3 New</i> | 2 | \$ 36.00 | \$ 72.00 | + |
| 48 | Rear Quarter Glass Moulding with Chrome Strip LH / RH <i>Not New</i> | 2 | \$ 448.00 | \$ 896.00 | + |

TOTAL PRICE : \$ 14,656.00

LIST LESS 10% : \$ 1,465.60

SUB TOTAL PRICE : \$ 13,190.40

7061
6354.90

CLAIM DETAIL : PARTS S/NETT

| S/N | DESCRIPTION | QTY | UNIT S/N PRICE | TOTAL S/N PRICE | |
|-----|---|-----|----------------|---------------------|----|
| 1 | Rear Bumper Clips <i>New</i> | 1 | \$ 50.00 | \$ 50.00 | 30 |
| 2 | Tailgate Centre Garnish Clip <i>New</i> | 1 | \$ 40.00 | \$ 40.00 | 20 |
| 3 | Tailgate Windscreen Sealant <i>New</i> | 1 | \$ 80.00 | \$ 80.00 | 60 |
| 4 | Tailgate Inner Trim Board Clip <i>New</i> | 1 | \$ 80.00 | \$ 80.00 | + |
| 5 | Tailgate Inner Upper Trim LH / RH Clip <i>3 New</i> | 1 | \$ 58.00 | \$ 58.00 | + |
| 6 | Tailgate Inner Upper Trim Centre Clip <i>3 New</i> | 1 | \$ 40.00 | \$ 40.00 | + |
| 7 | Rear End Panel Top Garnish Clips <i>New</i> | 1 | \$ 80.00 | \$ 80.00 | 20 |

| | | | | | |
|-----|--|---|------------------------------|----------------------|----|
| 8 | Rear Quarter Glass Moulding Sealant <i>new</i> | 1 | \$ 80.00 | \$ 80.00 | + |
| 9 | Rear End Panel Sealant <i>new</i> | 1 | \$ 60.00 | \$ 60.00 | ✓ |
| 10 | Tailgate "C&C" Logo badge <i>new</i> | 1 | \$ 168.00 | \$ 168.00 | 50 |
| 11 | Tailgate Solar Film <i>new</i> | 1 | \$ 388.00 | \$ 388.00 | + |
| 12 | Reverse Camera <i>new</i> | 1 | \$ 680.00 | \$ 680.00 | + |
| 13 | Reverse Sensor <i>Dmg.</i> | 1 | \$ 320.00 | \$ 320.00 | 2w |
| 440 | | | S/N TOTAL PRICE: \$ 2,124.00 | | |

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

| S/N | DESCRIPTION | PRICE | ADJUST |
|-----|---|------------------------|--------|
| 1 | To weld, cut, panel beat & straighten necessary areas and replace above mentioned parts | \$ 840.00 | 800 |
| 2 | To putty and spray paint Tailgate, Rr Bumper, Rr Bumper Lower Spoiler, Rr End Panel, Rr Floor Panel, Rr LH & RH Fender and other affected areas | \$ 1,380.00 | 900 |
| 3 | To apply rust proofing and undercoat | \$ 180.00 | 60 |
| 4 | To check and diagnose rear wiring and electrical components | \$ 80.00 | 30 |
| 5 | To remove and refit upholstery, cushion and seats to facilitate repair procedures | \$ 350.00 | 80 |
| 6 | Remove and refit tailgate windscreen | \$ 120.00 | ✓ |
| 7 | Remove and refit Rear LH / RH Quarter Glass to facilitate repair | \$ 380.00 | + |
| 8 | Labour charge to transfer tailgate mechanism | \$ 80.00 | ✓ |
| 9 | To perform water leakage test | \$ 100.00 | + |
| 10 | To reset and calibrate with parameter setting for affected rear control unit modules | \$ 280.00 | + |
| 11 | To install reverse camera with calibration and settings | \$ 120.00 | 50 |
| 12 | To install rear reverse parking sensor with calibration | \$ 120.00 | 50 |

LABOUR TOTAL PRICE: \$ 4,030.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2170
Adrian Lij
Total: 8964.50 r/s 29/03/21.
L/s: 7.1K ✓ 06 Dmgs