



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

16/4/2021

Survey Details:

Date of loss	24-Mar-21
Date of appointment	29-Mar-21
Date of survey	30-Mar-21
Location of survey	Thong Sheng Motors

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	JSP 9061
Make and Model	Yamaha 135 LC
Date of registration	12/2/2018
Excess	-
Market Value	\$ 1,800.00
Part Rebate	\$ -
Nett Loss	\$ 1,800.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	4
----------------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$2,000.00 - \$2,500.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	