


ASS. REC. BY: ad AK (2008)

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Car City Auto
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: \$50k
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT



Veh No: STD 20590 Yr Regn: 13 Mar 2008
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mit Lancer 2.0 c.c. 1998
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 148780 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: IMYSTCY PA8U 0028214
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45 R17
R: 4
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 26-03-21
Survey held at w/s 4pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>COE: 35788</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
1) _____
Date/Time, File Return to? _____
2) _____
Report Forwarded _____
Report Date / Time _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$) _____
☐ : Interview (\$) _____
☐ : Tech. Insp (\$) _____
☐ : Misc. Insp (\$) _____

Survey Fee: _____
Transportation: _____
3 + RS. \$ _____
Photos _____
Other: _____
TOTAL _____



CAR CITY AUTO CENTRE PTE LTD

Car City Always

TO : CAAIG0001

AIG Asia Pacific Insurance Pte Ltd
NO 78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120
TEL : 64193000 FAX :
PH :
ATTN :

ESTIMATE BILL

GST Registration : 200719980C

Number : EB00000303

Date : 26/03/2021

Case No : AD00000791

Vechicle No : SJD2059D

Mileage :

Term: M.J. Lancer 2.0L

Model :

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	REAR BUMPER REINFORCEMENT <i>BT</i>	1.0	479.00	10.00	431.10
2	REAR BUMPER REINFORCEMENT BRACKET RH & LH <i>XNN</i>	2.0	145.20	10.00	261.36
3	REAR BUMPER BRACKET <i>XNN</i>	2.0	68.40	10.00	123.12
4	REAR BUMPER RETAINER LH & RH <i>BT CMA</i>	2.0	74.60	10.00	134.28
5	REAR BUMPER REFLECTOR RH & LH <i>BT XNN</i>	2.0	118.20	10.00	212.76
6	REAR BUMPER TOW GARNISH <i>XNN</i>	1.0	43.50	10.00	39.15
7	REAR BUMPER NUMBER PLATE LAMP <i>XNN</i>	2.0	55.40	10.00	99.72
8	REAR BOOTLID <i>BT</i>	1.0	993.50	10.00	894.15
9	REAR BOOTLID HIGNES RH & LH <i>XNN</i>	2.0	48.20	10.00	86.76
10	REAR BOOTLID DAMPER RH & LH <i>XNN</i>	2.0	175.60	10.00	316.08
11	REAR BOOTLID WEATHER STRIP <i>BT</i>	1.0	310.20	10.00	279.18
12	REAR BOOTLID INNER LOCK <i>BT</i>	1.0	368.20	10.00	331.38
13	REAR BOOTLID CENTRE BRAKE LAMP (LED) <i>CMA</i>	1.0	320.60	10.00	288.54
14	REAR BOOTLID LOGO <i>BT</i>	1.0	98.50	10.00	88.65
15	REAR BOOTLID EMBLEM (LANCER EX) <i>BT</i>	1.0	78.40	10.00	70.56
16	REAR BOOTLID EMBLEM (MIVEC) <i>BT</i>	1.0	98.50	10.00	88.65
17	REAR BOOTLID EMBLEM (MIVEC -SMALL) <i>BT</i>	1.0	78.20	10.00	70.38
18	REAR BOOTLID LAMPS RH & LH <i>BT XNN</i>	2.0	584.10	10.00	1,051.38
19	REAR BOOTLID INNER TRIM GARNISH <i>BT XNN</i>	1.0	295.70	10.00	266.13
20	REAR TAILLAMP RH & LH <i>BT XNN</i>	2.0	725.60	10.00	1,306.08
21	REAR TAILLAMP PANEL RH & LH <i>BT XNN</i>	2.0	296.00	10.00	532.80
22	REAR FENDER RH & LH <i>BT XNN</i>	2.0	1,200.00	10.00	2,160.00
23	REAR FENDER INNER TRIM GARNISH RH & LH <i>BT XNN</i>	2.0	425.70	10.00	766.26
24	REAR FENDER INNER SHIELD RH & LH <i>BT XNN</i>	2.0	195.40	10.00	351.72
25	REAR END PANEL <i>BT</i>	1.0	722.80	10.00	650.52
26	REAR END PANEL TOP GARNISH <i>BT</i>	1.0	256.70	10.00	231.03
27	REAR EXHAUST PIPE <i>XNN</i>	1.0	925.60	10.00	833.04
28	REAR EXHAUST PIPE MOUNTING <i>XNN</i>	3.0	75.50	10.00	203.85

E. & O. E.

CAR CITY AUTO CENTRE PTE LTD



Page 1/3

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Page 1 of 3

* N = Item not subjected to GST

Issued by : Ho

Service Centre
Blk 9006 Tampines Street 93
#01-198 Singapore 528840
Tel: 6781 0300 Fax: 6782 0300
24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg



CAR CITY AUTO CENTRE PTE LTD

Car City Always

TO : CAAIG0001

AIG Asia Pacific Insurance Pte Ltd
NO 78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120
TEL : 64193000 FAX :
PH :
ATTN :

ESTIMATE BILL

GST Registration : 200719980C

Number : EB00000303

Date : 26/03/2021

Case No : AD00000791

Vehicle No : SJD2059D

Mileage :

Term:

Model :

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
29	REAR EXHAUST PIPE HEAT SHIELD X NV	1.0	255.40	10.00	229.86
30	REAR SPARE TYRE PANEL TOP BOARD / CMA	1.0	295.80	10.00	266.22
31	REAR SPARE TYRE PANEL X Repair	1.0	986.70	10.00	888.03
32	REAR WINDSCREEN GLASS MOULDING X NV	1.0	245.00	10.00	220.50
List Price - Parts Sub Total					13,773.24
33	REAR FENDER INNER TRIM GARNISH CLIPS(2 SETS) / MC	1.0	90.00	0.00	90.00
34	REAR FENDER INNER SHIELD CIPS (2 SETS) X NV	1.0	110.00	0.00	110.00
35	REAR END PANEL TOP GARNISH CLIPS / MC	1.0	35.00	0.00	35.00
36	REAR BOOTLID INNER TRIM CLIPS	1.0	45.00	0.00	45.00
37	REAR BUMPER (AFTER MARKET - ACCESSORIES)	1.0	1,800.00	0.00	1,800.00
38	REAR BOOTLID STICKER (RAILLIART)	1.0	110.00	0.00	110.00
39	REAR BOOTLID EMBLEM (EVOLUTION RALLIART)	1.0	168.40	0.00	168.40
40	REAR BOOTLID EMBLEM (C & C)	1.0	55.00	0.00	55.00
41	REAR BOOTLID CENTRE BRAKE LENS(ACCESORIES -LANCER EX)	1.0	145.00	0.00	145.00
42	REAR EXHAUST PIPE CHROME MUFFLER X NV	1.0	125.00	0.00	125.00
43	REAR NUMBER PLATE W/GARNISH	1.0	55.00	0.00	55.00
44	REVERSE SENSORS / NBL	1.0	250.00	0.00	250.00
45	REAR BOOTLID DUCKTAIL	1.0	600.00	0.00	600.00
46	REAR BOOTLID SEALANT X NV	1.0	100.00	0.00	100.00
47	REAR BOOTLID TRIANGEL EMBLEM / NBL	1.0	200.00	0.00	200.00
48	REAR WINDSCREEN SEALANT X NV	1.0	40.00	0.00	40.00
49	REAR SPARE TYRE PANEL RUBBER INSULATOR X NV	1.0	400.00	0.00	400.00
Special Nett Price - Parts Sub Total					4,328.40
Parts Total					18,101.64
50	TO REMOVE, REPLACE, REALIGN & INSTALL AFFECTED REAR DAMAGED AREAS	1.0	1,400.00	0.00	1,400.00

E. & O. E.

CAR CITY AUTO CENTRE PTE LTD

Page 2/3

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Page 2 of 3

* N = Item not subjected to GST

Issued by : Ho

Service Centre
Blk 9006 Tampines Street 93
#01-198 Singapore 528840
Tel: 6781 0300 Fax: 6782 0300
☎ 24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg



CAR CITY AUTO CENTRE PTE LTD

Car City Always

TO : CAAIG0001

AIG Asia Pacific Insurance Pte Ltd
NO 78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120
TEL : 64193000 FAX :
PH :
ATTN :

ESTIMATE BILL

GST Registration : 200719980C

Number : EB00000303

Date : 26/03/2021

Case No : AD00000791

Vehicle No : SJD2059D

Mileage :

Term:

Model :

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
51	To putty, prep & respray on affected rear damaged ares..rear bootlid, rear end panel,	1.0	1,400.00	0.00	1,400.00
52	To remove & transfer rear bootlid components to facilitate repairs	1.0	200.00	0.00	200.00
53	To remove rear interior components to facilitate repairs	1.0	200.00	0.00	200.00
54	To remove & install & align rear exhaust pipe	1.0	150.00	0.00	150.00
55	To conduct & check on all affected electrical wiring	1.0	150.00	0.00	150.00
56	To reposition, align & install reverse sensors	1.0	150.00	0.00	150.00
57	To conduct rera water seepage test	1.0	150.00	0.00	150.00
58	To provide rust coatings on affected areas	1.0	200.00	0.00	200.00
59	to reset & calibrate ECU diagnostice	1.0	250.00	0.00	250.00
60	To remove/refix rear windscreen glass	1.0	150.00	0.00	150.00
61	Towing from accident site to workshop	1.0	50.00	0.00	50.00
Labour 1 Sub Total					4,450.00
SINGAPORE DOLLARS : TWENTY-FOUR THOUSAND ONE HUNDRED THIRTY AND CENTS TWENTY-FIVE ONLY					
SUBTOTAL					22,551.64
GST 7.00%					1,578.61
TOTAL					24,130.25

6-7 Days.
Imp sm repair
After repair photos.
Gene Qian - 82880282

120c
60
60
X NN
30
40
X NN
60
X NN
X NN
/

Date of accident : 25/03/2021 01:30 PM. Place : YIO CHU KANG TOWARD SENGKANG ROAD

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

CUSTOMER SIGNATURE

CAR CITY AUTO CENTRE PTE LTD

AUTHORISED SIGNATURE

* N = Item not subjected to GST
Acknowledged by Repairer

Service Centre Signature:
Blk 9006 Tampines Street 93
#01-198 Singapore 328840
Tel: 6781 0300 Fax: 6782 0300
24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg

Issued by : Ho