

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004013/KPA3Q2
Date: 06/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100460055
Claimant Vehicle No :	SKZ3609H	Insured Vehicle No :	SLB3877P
Date of Loss:	27/03/2021	Nature of Claim:	TP
		Claim No:	9075995674SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ3609H	Engine No:	1ZZ3067737
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZNE100401647
Reg. Date:	09/04/2008 (Man. Year: 2008)	Odometer:	204796 km
Colour:	Metallic Black		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,449.92	1,648.87	1,801.05	52.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,788.00	1,220.00	568.00	31.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,237.92	2,868.87	2,369.05	45.23
Approved Total (Overridden) (S\$)		2,300.00		

(S\$)	5,237.92	2,300.00	2,937.92	56.09
+ GST 7.00/7.00% (S\$)	366.65	161.00	205.65	56.09
Nett Amount (S\$)	5,604.57	2,461.00	3,143.57	56.09
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		2,961.00		
Global Sum Settlement (S\$)		2,960.00		

INSPECTION

Date of Assignment: 29/03/2021

Date Inspected: 19/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming AutoCity
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Bent	1,109.00 FL	*1,109.00 FL
2	1		*RH REAR DOOR	Bent	1,089.50 FL	*1,089.50 FL
3	1		*RH REAR DOOR LOWER HINGE	Repair	120.30 FL	*- FL
4	1		*RH REAR DOOR INNER LOCK	Repair	345.60 FL	*- FL
5	1		*RH REAR WHEEL RIM	Repair	1,197.10 FL	*- FL
6	1		*RH REAR WHEEL BEARING	Serviceable	450.90 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,312.40	2,198.50
- List Item Discount on L Items 20.00/25.00% (\$)	862.48	549.63
Total Parts (\$)	3,449.92	1,648.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE AND REFIX TYRE	New	18.00	0.00
2	TO PERFORM COMPUTERISED WHEEL ALIGNMENT	New	80.00	60.00
3	TO REMOVE AND FRIX REAR RH WHEEL UNDERCARRIAGE	New	180.00	0.00
4	TO APPLY ANTI-CORROSION TUFF KOTE	New	80.00	60.00
5	TO REMOVE DAMAGED PARTS ,TO CUT OUT DAMAGED PARTS ,TO REWELD ,RESHAPE AND REPAIR RH REAR FENDER ,TO REPLACE DAMAGED COMPONENTS ,RH FRONT AND REAR DOOR AND ADJUST BODY PANEL ALIGNMENT	New	580.00	500.00
6	TO SPRAY PAINT RH FRONT AND REAR DOOR ,RH REAR FENDER AND REAR BUMPER AND AFFECTED DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	850.00	600.00
Gross Labour Cost (S\$)			1,788.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >