

26 LILAC DRIVE
LILAC PARK
SINGAPORE 808216



File No : SH/2021/03470/7007/TP
Date : 19-April-2021

*Not Wished
L1 Lp & 2300h
Purung After Paint 4 days*

Estimated cost of repair for vehicle no : SKZ3609H Model TOYOTA WISH
Accident involving vehicle no: SGS19B & SLB3877P on 27.03.2021

Description	Quantity	Cost Price
RH front door	1	\$ <i>R</i> 1,109.00 ✓
RH rear door	1	\$ <i>R</i> 1,089.50 ✓
RH rear door lower hinge	1	\$ <i>n</i> 120.30 X
RH rear door inner lock	1	\$ <i>n</i> 345.60 X
RH rear wheel rim	1	\$ <i>Pen n</i> 1,197.10 X
RH rear wheel bearing	1	\$ <i>Pen</i> 450.90 X
		<i>25%</i> \$ 4,312.40
	Less 20%	\$ 862.48
		\$ 3,449.92
Labour to remove and refix tyre	1	\$ <i>nn</i> 18.00 X
To perform computerised wheel alignment.	1	\$ 80.00 <i>600</i>
To remove and frix rear RH wheel undercarriage.	1	\$ <i>nn</i> 180.00 X
To apply anti-corrosion tuff kote.	1	\$ 80.00 <i>600</i>
To remove damaged parts, to cut out damaged parts, to reweld , reshape and repair RH rear fender, to replace damaged components, RH front and rear door and adjust body panel alignment.		\$ 580.00 <i>500</i>
To spray paint RH front and rear door, RH rear fender and rear bumper and affected damaged portion inclusive of preparatory works and material.		\$ 850.00 <i>600</i>
		\$ 5,234.92

T/Party: AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: