

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD9402Z**AAD2103-134***Not Authorised**Return By pain**8712.23*

Vehicle No.:

30 MAR 2021**SHD9402Z**

Chassis No.:

JTDKB3FU303079466

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS

Date of Accident:

27/03/2021

Third Party Insurer:

AUTO & GENERAL

Date of Registration:

11/03/2019

PART**LIST**

1 COVER, REAR BUMPER	\$	442.60	X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70	X
1 COVER, REAR BUMPER, LOWER	\$	15.40	X
1 GUARD, REAR BUMPER, CENTER	\$	576.30	X
1 RETAINER, REAR BUMPER SIDE, LH	\$	116.50	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	117.70	X
1 FILLER, REAR BUMPER EXTENSION, LH	\$	123.70	X
1 FILLER, REAR BUMPER EXTENSION, RH	\$	123.70	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30	X

TOTAL \$ 2,498.90**25% \$ 624.73****\$ 1,874.18****Special Nett**

1SET PARKING AID

\$ 700.00 X

1SET REAR BUMPER CLIP

\$ 95.00 X

TOTAL \$ 795.00**TOTAL PARTS \$ 2,669.18****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *601*

Trans-cab Auto Services Pte Ltd**AAD2103-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9402Z

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 X

Towing Fees

\$ 150.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 2200

To reinstall rear bumper parking sensor.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 X

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ 220.00 X

To replace, refix and top up coolant for radiator

\$ 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9402Z

AAD2103-134

To lift-up / out engine with gear box and refit.

\$ 440.00 X

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

\$ 380.00 X

TOTAL \$ 9,610.00

Over All Total \$ 12,279.18

(PART-BY-PART) Repair Days

25 DAYS

1 1/2 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: