


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Trans Cob
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 1 1/2 days Res.: Yes or No
 Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S1TD 94027 Yr Regn: 03, 19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toy Prius c.c. 1798
 Colour: M.P. White / Red A/C: Insured / Std / NI / NA
 Sp. Reading: 180422 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTD KB 3FU 303079466
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rlm / STD / Rlm or _____
 Tyre Size: F: 195/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Sailun

Front Rear
 R/Bal. 9 mm R/Bal. 9 mm
 L/Bal. 9 mm L/Bal. 9 mm
 D.O.A. 27/3/21 D.O.I. 30/3/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassals frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>30/3</u>	<u>8712.23</u> <u>Cash</u>

Date/Time, File Pass to? ☐ : Prell. Report

1) ☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Others

Others

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Invs (\$ _____)

☐ : Weekend (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9402Z**AAD2103-134**

Not Authorised
Return By 8/12/23

Vehicle No.:

30 MAR 2021**SHD9402Z**

Chassis No.:

JTDKB3FU303079466

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS

Date of Accident :

27/03/2021

Third Party Insurer :

AUTO & GENERAL

Date of Registration:

11/03/2019

PART**LIST**

1 COVER, REAR BUMPER	\$	442.60	X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70	X
1 COVER, REAR BUMPER, LOWER	\$	15.40	X
1 GUARD, REAR BUMPER, CENTER	\$	576.30	X
1 RETAINER, REAR BUMPER SIDE, LH	\$	116.50	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	117.70	X
1 FILLER, REAR BUMPER EXTENSION, LH	\$	123.70	X
1 FILLER, REAR BUMPER EXTENSION, RH	\$	123.70	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30	X

TOTAL \$ 2,498.90**25% \$ 624.73****\$ 1,874.18****Special Nett**

1SET PARKING AID

\$ 700.00 X

1SET REAR BUMPER CLIP

\$ 95.00 X

TOTAL \$ 795.00**TOTAL PARTS \$ 2,669.18****LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion,
 Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *601*

Trans-cab Auto Services Pte Ltd**AAD2103-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9402Z

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 X

Towing Fees

\$ 150.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 2200

To reinstall rear bumper parking sensor.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 X

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ 220.00 X

To replace, refix and top up coolant for radiator

\$ 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9402Z

AAD2103-134

To lift-up / out engine with gear box and refit.

\$ 440.00 X

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

\$ 380.00 X

TOTAL \$ 9,610.00

Over All Total \$ 12,279.18

(PART-BY-PART) Repair Days

25 DAYS

1 1/2 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/03/2021 11:25 (SGT)
Date of Accident	27/03/2021 07:40 (SGT)
Exact Location of Accident	Bedok North Rd, Singapore
Additional Location Information	JUNCTION OF BEDOK NORTH ROAD AND BEDOK RESERVOIR ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9402Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	Claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62866666
Alternative Phone No	(Office) +65-62866666

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1767

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	VFX/P2413997
Cover Note Number	-

DRIVER


Name of Driver	SEOW LIANG HUA
----------------	----------------

SKETCH PLAN

Bedok
North
Road

A: 91D94022

B: SLK1577L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
CP1

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG BEDOK RESERVOIR ROAD TOWARDS BEDOK NORTH ROAD . BEFORE TURNING RIGHT INTO BEDOK NORTH ROAD , I STOPPED MY VEHICLE AT THE JUNCTION WAITING THE TRAFFIC LIGHT . SUDDENLY VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE . NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

29 March 2021 at 9:11 AM

Date/Time:

29 March 2021 at 9:11 AM