



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

26/04/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPFrgo

Veron.

Accident date: 26/03/2021

Estimated repair cost for vehicle no: SBX8860G MERCEDES BENZ GLB200 PROGRES

CHASSIS: W1N2476872W054320

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front R/H Door		\$3,120.00 +
2	1	Front R/H Door Hinge	\$185.00	\$185.00 +
3	2	Front R/H Door Frame Sticker	\$150.00	\$300.00 +
4	1	Rear R/H Door Dented		\$2,920.00 2800
5	2	Rear R/H Door Hinge	\$185.00	\$370.00 +
6	2	Rear R/H Door Frame Sticker	\$150.00	\$300.00 60
7	1	Rear R/H Door Outer Handle		\$480.00 +
8	1	Rear R/H Door Side Arch Garnish		\$235.00 ✓
9	1	Rear R/H Door Lower Protector		\$524.20 ✓
10	1	Rear R/H Door Inner Lock		\$328.00 +
11	1	Rear R/H Door Inner Trim Board		\$1,985.00 +
12	8	Rear R/H Door Inner Trim Board Clip	\$6.50	\$52.00 +
13	1	Rear R/H Door Weatherstrip		\$325.00 + 280
14	1	Rear R/H Door Window Regulator Motor Assy		\$1,085.00 +

3899.20

3509.28

3004.20

2703.78

Subtotal:- \$12,209.20

Labour charges

To remove & refit rear R/H door, lock, glass, weatherstrip, trim board, frame sticker & window motor regulator

\$450.00 80

To remove & refit front R/H door, lock, glass, weatherstrip, trim board, frame sticker & window motor regulator

\$450.00 X

To check wiring

\$100.00 X 30

Tuff kote

\$100.00 X

Panel beating

Spray painting

700

\$1,600.00 ~~300~~

~~480~~

\$1,400.00 ~~250~~

Subtotal :- \$4,100.00

Total:- \$16,309.20

~~total: 3183.78~~

~~(CP/P)~~

03 Days.

total: 4209.28

(CP/P).

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: