

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref: Own Damaged

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way, #11-16 Singapore
79120

Date : 26.03.2021



NOT Notified
Repairing Be paint

12 days

Vehicle No : SMN64M
Chassis No : WBSLX92030C968143
Make/Model : BMW M6
Year : 2013

S/N	Qty	Description	Unit Price	10%	Amount
1	1pc	FRONT BONNET	\$ 2,150.00	10%	\$ 2,365.00
2	1pc	FRONT BUMPER TOP GARNISH (LH)	CM \$ 215.00	10%	\$ 237.00
3	1pc	FRONT SUPPORT TOP PANAL (BLACK)	Bu \$ 160.00	10%	\$ 176.00
4	1pc	FRONT BUMPER EMBLEM "LOGO"	me \$ 65.00	10%	\$ 72.00
5	1pc	FRONT BUMPER AIR DUCT	CM \$ 260.00	10%	\$ 286.00
6	1pc	FRONT HEADLAMP LH	my CM \$ 4,300.00	10%	\$ 4,730.00
7	1pc	FRONT HEADLAMP RH	l \$ 4,300.00	10%	\$ 4,730.00
8	1pc	FRONT HEADLAMP LOWER BRACKET LH	CRA \$ 120.00	10%	\$ 132.00
9	1pc	FRONT HEADLAMP LOWER BRACKET RH	CM \$ 120.00	10%	\$ 132.00
10	1pc	FRONT BUMPER	Bz \$ 1,900.00	10%	\$ 2,090.00
11	1pc	FRONT BUMPER RADIATOR GRILLE LH	CM \$ 115.00	10%	\$ 127.00
12	1pc	FRONT BUMPER RADIATOR GRILLE RH	CM \$ 115.00	10%	\$ 127.00
13	1pc	FRONT BUMPER NOZZLE COVER LH	\$ 45.00	10%	\$ 50.00
14	1pc	FRONT BUMPER NOZZLE COVER RH	\$ 45.00	10%	\$ 50.00
15	1pc	FRONT BUMPER NOZZLE WASHER LH	\$ 105.00	10%	\$ 116.00
16	1pc	FRONT BUMPER NOZZLE WASHER RH	\$ 105.00	10%	\$ 116.00
17	1pc	FRONT BUMPER NOZZLE SUPPORT LH	\$ 15.00	10%	\$ 17.00
18	1pc	FRONT BUMPER NOZZLE SUPPORT RH	\$ 15.00	10%	\$ 17.00
19	1pc	FRONT BUMPER TOWING COVER	miy \$ 55.00	10%	\$ 61.00
20	4pc 2	FRONT BUMPER SENSOR	Short IDJ \$ 720.00	10%	\$ 792.00
21	4pc	FRONT BUMPER SENSOR SEAL	me \$ 20.00	10%	\$ 22.00
22	1pc	FRONT BUMPER VIEW CAMERA LH	\$ 350.00	10%	\$ 385.00
23	1pc	FRONT BUMPER VIEW CAMERA RH	\$ 350.00	10%	\$ 385.00
24	1pc	FRONT BUMPER LOWER SEAL	fu \$ 165.00	10%	\$ 182.00
25	1pc	FRONT BUMPER NUMBER PLATE	CRA \$ 18.00	10%	\$ 20.00
26	1pc	FRONT BUMPER NUMBER PLATE CASING	nd \$ 25.00	10%	\$ 28.00
27	1pc	FRONT BUMPER BRACKET LH	diy \$ 10.00	10%	\$ 11.00
28	1pc	FRONT BUMPER BRACKET RH	diy \$ 10.00	10%	\$ 11.00

Grand Total

\$ 15,873.00

\$ 17,467.00

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref: Own Damaged

Date :

26/3/2021

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY, #27-01/02

Vehicle No : SMN64M
Chassis No : WBSLX92030C968143
Make/Model : BMW M6
Year : 2013

S/N	Qty	Description	Unit Price	10%	Amount
Grand Total:			\$ 15,873.00		\$ 17,467.00
29	1pc	FRONT BUMPER REFORCEMENT	\$ 680.00	10%	\$ 748.00
30	1pc	FRONT BUMPER SPONCE	\$ 80.00	10%	\$ 88.00
31	1pc	FRONT BUMPER REFORCEMENT " L " BRACKET LH	\$ 18.00	10%	\$ 20.00
32	1pc	FRONT BUMPER REFORCEMENT " L " BRACKET RH	\$ 18.00	10%	\$ 20.00
33	1pc	FRONT FENDER LH	\$ 900.00	10%	\$ 990.00
34	1pc	FRONT FENDER RH	\$ 900.00	10%	\$ 990.00
35	1pc	FRT BUMPER LOWER GRILLE INNER AIR DUCT LH	\$ 85.00	10%	\$ 94.00
36	1pc	FRT BUMPER LOWER GRILLE INNER AIR DUCT RH	\$ 85.00	10%	\$ 94.00
37	1pc	AIR BAG ROOF SIDE LH	\$ 780.00	10%	\$ 858.00
38	9pc	AIR BAG ROOF SIDE RIVIT	\$ 23.00	10%	\$ 26.00
39	1pc	FRONT PASSAGE AIR BAG	\$ 1,450.00	10%	\$ 1,595.00
40	1pc	FRONT STEERING AIR BAG	\$ 1,850.00	10%	\$ 2,035.00
41	1pc	FRONT STEERING CLOCK SPRING	\$ 690.00	10%	\$ 759.00
42	1pc	FRONT DACH BOARD	\$ 5,750.00	10%	\$ 6,325.00
43	1pc	FRONT SEAT BELT RH	\$ 530.00	10%	\$ 583.00
44	1pc	FRONT SEAT BELT LH	\$ 530.00	10%	\$ 583.00
45	1pc	FRONT SEAT BELT BUCKLE LH	\$ 290.00	10%	\$ 319.00
46	1pc	FRONT SEAT BELT BUCKLE RH	\$ 290.00	10%	\$ 319.00
47	1pc	FRONT SEAT HEADREST SENSOR LH	\$ 110.00	10%	\$ 121.00
48	1pc	FRONT SEAT HEADREST SENSOR RH	\$ 110.00	10%	\$ 121.00
49	1pc	ROOF LINNING	\$ 1,680.00	10%	\$ 1,848.00
50	1pc	REAR BATTERY (PLUS POLE)	\$ 250.00	10%	\$ 275.00
51	2pc	FRONT AIR BAG SENSOR	\$ 210.00	10%	\$ 231.00
52	1pc	AIR BAG COMPUTER	\$ 1,080.00	10%	\$ 1,188.00
Grand Total			\$ 34,262.00		\$ 37,697.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref: Own Damaged

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY, #27-01/02

Date : 26/3/2021

Vehicle No : SMN64M
Chassis No : WBSLX92030C968143
Make/Model : BMW M6
Year : 2013

S/N	Qty	Description	Unit Price	10%	Amount
Material Grand Total			\$ 34,262.00		\$ 37,697.00

Labour Charges

1 To vacuum and refill gas	\$ 150.00	100d
2 To conduct re-programme and setting of ecu system to clear fault code	\$ 480.00	30d
3 To remove & install replace radiator , cooling system & all necessary parts to facilitate repair , including pressure test , bleed cooling system & check leaks	\$ 800.00	70d
4 To check electrical wiring system of frontsection for proper function including adjustment of headlamp	\$ 150.00	30d
5 To jasking of chassis and mounting of car on celett bench and cutting and welding , knocking accident front portion front bonnet , front bumper , support panal and front fender lh / rh	\$ 1,800.00	?
6 To respray front accident portion front bonnet , front bumper , front fender lh / rh	\$ 2,000.00	125d
7 To towing accident vehicle to workshop	\$ 120.00	?
8 To remove & replace roof top cover	\$ 300.00	15d
9 To remove & replace air bag roof side	\$ 300.00	} 25d
10 To remove & replace front steering air bag	\$ 250.00	
11 To remove & refix undercarriage front seat belt lh / rh , headrest lh / rh headrest sensor lh / rh and seat belt buckle lh / rh	\$ 650.00	30d
12 To remove battery cable (plus pole)	\$ 250.00	6d
13 To remove & replace front dash board	\$ 600.00	30d

Labour Grand Total

\$ 45,547.00

Your Faithfully,

Wega Engineering Pte Ltd

Leong Kwee Kwong *

Claims Advisor

