

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09356/ANG HWE KHENG Reg No/Reg Date SME2357C / 24/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003044 Engine No 3A92UHG4358 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	29/03/2021/ 17:25	BLE	261 / Edwin Caina	64574		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHR DOOR, RR BUMPER & RR BUMPER BODY KIT REPAIR LHF DOOR & LHR FENDER				2 1/2 x 80			1205 2700.00
E PNT98000 RESPRAY LHF DOOR, LHR DOOR, LHR FENDER, RR BUMPER & RR BUMPER BODY KIT				5 x 350			1750.00
E PNT88000 REMOVE & REFIT LHR DOOR COMPONENT							120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT (photo)							120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR							60.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							40 60.00
M SUNDRY SUPPLY BODY PNL SEALANT							20.00
M SUNDRY Sundries							
M PANEL ASSY, RR DOOR, LH				1.00	803.00	23.00	618.31
M MLDG, R/DR WDO BELT LINE, LH				1.00	76.00	23.00	58.52
M TAPE, RR DOOR SASH, LH				1.00	29.00	23.00	22.33
M REGULATOR, R/DR WINDOW, LH				1.00	132.00	23.00	101.64
M MOTOR, R/DR PWR WDO RGLTR, R				1.00	391.00	23.00	301.07
M BRACKET, RR BUMPER, LH				1.00	28.00	23.00	21.56
M CLIP, RR BUMPER				4.00	4.00	23.00	12.32
M FACE, RR BUMPER				1.00	751.00	23.00	578.27
M UNPAINTED BODYKITS				1.00	1643.00	20.00	1314.40

Estimate

30/3/21, 2:00pm

Steve CLKK

00-14 AL

SURVEYOR NAME:

SURVEYOR NAME: Steve CLKK

Confirm & accepted by

SURVEYOR SIGNATURE: Exori - ?

DATE: P/P, R/L Bel SN

REMARKS: 7 days

Nett

8048.42

8,048.42

563.39

Total Payable

8,611.81

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.